


Introduction to Synchronous Generators :-

Introduction :-

- Synchronous machines are electro-mechanical energy converters and involves the interchange of energy bet'n an electrical and mechanical system.
- These machines are called synchronous machines because they operate at constant speeds & constant frequencies under steady state conditions.
- The primary quantities involved in the mechanical system are torque and speed.
- The analogues quantities with electrical system are voltage & current respectively, as shown in figure.



[Block diagram for electro - Mechanical Energy conversion]

- Motor action results when the electrical system causes a current 'i' to flow through the conductors that are placed in a magnetic field.
- A force is produced on each conductor so, that if the conductors are located on a structure that is free to rotate an electro-magnetic torque "T" results which in turn manifests it self as an angular velocity w_m .

- The development of this motor action the revolving conductors cut through the magnetic field, thereby undergoing an electro-motive force 'e' which is really a reaction voltage analogous to the induced emf in the primary of a transformer.
- Note that the coupling field is involved in establishes the electromagnetic torque τ as well as the reaction induced emf. 'e'.
- The reverse process takes place here the rotating member the 'rotor' is driven by a prime mover.
- The induced voltage 'e' to appear across the armature winding terminals.
- The current 'I' is made to flow, delivering electrical power to the load.
- The flow of this current through the armature conductors interacts with the magnetic field to produce a reaction torque opposing the applied torque originating from the prime mover.
- It is emphasized that the character of this motor-generator action is in relationship with the coupling magnetic field that is produced in the air gap betⁿ the rotor & the stator of the machine.
- The most rotating machines, synchronous machines are capable of operating as both motor & generator.

Introduction to alternator :-

- An AC generating machine, is called an Alternator or AC generator.
- It is used to generate alternating emf in accordance with the Faraday's laws of electromagnetic induction.
- When ever a conductor is rotated in a magnetic flux, then it cuts the magnetic lines of force, & an emf is induced in it.
- The working principle of an alternator is the same as that of a D.C. Generator.
- An alternator requires a magnetic flux, conductors and the mechanical power for generating the emf.
- The emf generated by the alternator is obtained through slip-rings or directly from the stator windings, depending on the type of alternator used.
- Generally the field of an alternator is excited with a D.C. Generator, which is mounted on the alternator's shaft. Hence an alternator is also known as separately excited generator.

Classification of Alternator :-

- On the basis of prime mover
 - Water turbine alternator
 - Steam turbine alternator
 - Oil engine alternator.
- On the basis of phase
 - single phase alternator,
 - Three phase alternator.

- On the basis of rotor :-
 - Rotating armature alternator
 - Rotating field.

Types of alternators :-

On the basis of prime mover :-

① Water turbine alternator :-

→ In this alternator, the rotor is rotated with the force of water.

- The water is stored in the form of a small lake by making a barrage on a river or canal.
- Then a water-fall is produced with the stored water, which rotates the turbine & which in turn rotates the rotor.
- The speed of this alternator is low due to low water speed, & thus to obtain the required frequency, the number of poles is to be kept more.

b) Steam turbine Alternator :-

- The force produced by steam is greater than that produced by water.
- The steam operates a steam - engine and the engine operates the alternator.
- The speed of this alternator is high.
- A 2-pole alternator can generate frequency of 50 c/s at 3000 R.P.M.

c) Oil Engine Alternators :-

- In this alternator, the rotor is rotated by a diesel or petrol operated engine. Since the system is expensive, therefore, it is used for such purposes where water or steam type alternators do not suit or for emergency purposes.

On the basis of phase :-

• Single phase alternator :-

- A small alternator used to generate the emf up to 250 Volts, for light & fan purposes, is usually single phase type.

• Three phase alternator :-

- This alternator can generate 650 to 6600 Volts or even more.
- It is used for light & fan as well as for power purposes.

Rotating Armature alternator :-

- It is similar to a generator in construction. It employs slip-rings in place of commutator.
- The poles are kept stationary, & the armature rotates betw the poles.

→ The emf is obtained through the slip-rings.
This alternator, usually has a low output capacity.

Rotating field alternator :-

→ In this alternator, the rotor contains the magnetic poles while the armature is kept stationary.
Hence, it can run at a high speed.

- Advantages of rotating field alternator:-
- Rotating field is comparatively light on weight & hence it can run at a high speed.
- Two slip rings of low current capacity are sufficient for its field excitation circuit.
- Higher voltages can be generated because of high speed of the rotor.
- It is easier to insulate armature coils design to work at high voltages, because these are placed in the stator portion.
- If the armature is kept rotating, then the high insulation of armature coils will make it bulky.
Hence, it will not be able to rotate at a high speed.
- The armature winding placed in star or delta system, can directly be connected to the distribution cables.

Advantages of polyphase alternators :-

- Poly phase alternators are small in size & economical in comparison to the single phase alternators, having the same output, voltage & frequency.

- A poly phase alternator has a constant armature reaction, while a single phase alternator has a pulsating armature reaction, under balanced load condition.
- poly phase transmission lines require less copper, in comparison to single phase transmission lines.
- The output power of a polyphase alternator is stable & non-pulsating for balanced load.
- A Poly-Phase alternator has a greater efficiency in comparison to a Single phase alternator.


Difference b/w DC Generator & alternator :-

- In case of a D.C Generator, basically the nature of the induced emf in the armature conductors is of alternating (A.C) type.
- By using commutators & brush assembly it is converted to D.C & made available to the external CKT.
- If commutator is removed from a DC generator and induced emf is collected with the help of slip rings & brushes from an armature directly outside to the external circuit, the nature of such emf will be alternating (A.C).
- Such a machine with out commutator providing an A.C emf to be the external circuit is called as an alternator.
- A Generator supplying an alternating circuit is known as alternator or AC generator.

PRINCIPLE OF OPERATION OF ALTERNATOR

(+) Working principle of synchronous generator :-


- The alternators work on the principle of electro magnetic induction.
- When there is a relative motion between the conductor and the flux, emf gets induced in the conductor.
- The DC Generators also work on the same principle.
- The only difference in practical alternators and a d.c. generator is that in an alternator the conductors are stationary and field is rotating.
- Consider a relative motion of a single conductor under the magnetic field produced by the two stationary poles.
- The magnetic axis of the two poles produced by field is vertical, shown dotted in the figure.



- let conductor starts rotating from position 1.
- The entire velocity component is parallel to the flux lines. Hence there is no cutting of flux line by conductor.

- The $\frac{d\phi}{dt}$ at this instant is zero and hence induced emf in the conductor is also zero.
- The conductor moves from position 1 towards position 2.
- The velocity component becomes perpendicular to the flux lines & proportional to that, emf gets induced in the conductor.
- The magnitude of such an induced emf increase as the conductor moves from position 1 towards 2.
- At position 2, the entire velocity component is perpendicular to the flux lines. Hence there exist maximum cutting of the lines.
- The induced emf in the conductor is as its maximum.
- The position of conductor changes from 2 towards 3.
- The velocity perpendicular to the flux starts decreasing and hence induced emf starts decreasing. magnitude also
- At position 3, again the entire velocity components is parallel to the flux lines & hence this instant induced emf in the conductor is zero.
- The conductor moves from position 3 towards 4.
- The velocity component perpendicular to the flux lines again starts increasing.
- The direction of velocity component ^{now} is opposite to the direction of velocity component existing during the movement of the conductor from position 1 to 2.
- The induced emf in the conductor increase but in the opposite direction.

- At position 4, it achieves maxima in the opposite direction, as the entire velocity component becomes perpendicular to the flux lines.
- The position 4 to 1 induced emf decrease & finally at position 1, again becomes zero. This cycle continues as conductor rotates at a certain speed.
- The magnitudes of the induced emf against the time, we get an alternating nature of the induced emf as shown in the fig. This is the working principle of an alternator.



(Alternating nature of the induced emf)

Introduction to alternator :-

- An AC generating machine, is called an alternator or AC generator.
- It is used to generate alternating emf in accordance with the Faraday's law of electro magnetic induction.
- Whenever a conductor is rotated in a magnetic flux, then it cuts the magnetic lines of force,

and an emf is induced in it.

- The working principle of an alternator is the same as that of a D.C generator.
- An alternator requires a magnetic flux, conductors and the mechanical power for generating the e.m.f.
- The e.m.f generated by the alternator is obtained through slip-rings or directly from the stator windings, depending on the type of alternator used.
- Generally the field of an alternator is excited with a DC Generator, which is mounted on the alternator's shaft. Hence an alternator is also known as a separately excited generator.

Classification of alternators :-

- ① On the basis of prime mover :-
 - (i) water turbine alternator
 - (ii) Steam turbine alternator
 - (iii) Oil engine alternators
- ② On the basis of phase :-
 - (i) single phase alternator
 - (ii) Three phase alternators.
- ③ On the basis of rotor :-
 - (i) Rotating armature alternator.
 - (ii) Rotating field.

Frequency of Induced E.M.F :-

Let,

p = Number of poles

N = Speed of rotors in R.P.M.

f = Frequency of the induced emf.

From the discussion, we can write

① One mechanical Revolution of Rotors
= $\frac{P}{2}$ cycle of emf electricity

② Thus there are $\frac{P}{2}$ cycles per revolution.

③ As speed in R.P.M., in one second, rotors will complete $(N/60)$ revolution.

But,

Cycles/sec. = Frequency (f)

$\therefore f = (\text{Number of cycle / revolution}) \times (\text{Number of revolution / sec.})$

$$\therefore f = \frac{P}{2} \times \frac{N}{60}$$

$$\therefore f = \frac{PN}{120} \text{ Hz (cycles / sec.)}$$

- So there exists a fixed relationship b/w 3 quantities, the number of poles (p).
- The speed of the rotors N in R.P.M. & f frequency obtain induced emf in Hz.

Synchronous Speed (Ns)

→ From the above expression, it is clear that for fixed number of poles, alternator has to be rotated at a particular speed to keep the frequency of the generated emf constant at the required value. Such a speed is called synchronous speed of the alternator denoted as Ns.

So,

$$N_s = \frac{120f}{P}$$

Where,

f = Required frequency

P = No of poles

- The frequency of an alternating emf is standard equal to 50 Hz To get 50 Hz.
- The different numbers of poles, alternators must be driven at different speeds called synchronous speeds.
- The following table gives that values of the synchronous speeds for the alternators having different numbers of poles.

Number of poles (P)	2	4	8	12	24
Synchronous speed Ns in r.p.m.	3000	1500	750	500	250


- The minimum number of poles for an alternator can be two hence maximum value of synchronous speed is possible i.e. for frequency of 50 Hz is 3000 r.p.m.

Construction of alternators

Construction & classification of Alternator :-

- The electrical machine, which generates alternating current & hence voltage is known as alternator or A.C. generator or synchronous generator.
- The following are the major parts of an alternator.

Stator frame
 Stator core }
 Stator winding } Stator or armature
 magnetic poles & field windings } field system
 Slip rings }
 Brush & Brush holder }
 Spider }
 Exciter }
 Shaft and bearings } Rotor




[ALTERNATOR]

- small AC generators are commonly made with stationary field magnet system & revolving armature.
- In large AC generators (Morden AC generators) the arrangement is reverse i.e. armature being stationary & field rotating.
- The advantages of stationary armature & that of the revolving field system are given below. :-
- No difficulty is experienced in insulating the stationary armature winding for even high voltage. e.g. as high as 30,000 V or more.
- The output current can be collected from fixed terminals on the armature or stator to the load.
- Two slip-rings are required for the supply of D.C. to the rotor & since exciting current is to be supplied at low voltage, there is no difficulty in insulating them.
- The armature windings can be more easily braced to prevent any deformation being produced by the mechanical stresses set up as a result of high centrifugal forces.
- Rotating field comparatively light & can run with high speeds.

STATOR :-

(i) Stator frame :-

- It is the outermost part of the machine. It is made of cast iron or cast steel or welded steel plates.
- Its main function is to give the mechanical protection to the entire machine and to hold the core in proper position.




④ Stator Core :-

- The stator core is laminated like a D.C. armature core.
- The laminations are formed of special magnetic iron or silicon steel having slots on its inner periphery to accommodate armature conductors.
- The whole structure is held in a frame or stator frame as shown in figure.
- Since the field rotates in the stator, so that flux of the rotating field cuts the core of the stator continuously and causes eddy current losses in the stator core.
- To minimize the eddy current losses the stator core is laminated.
- The laminations are stamped out in complete rings for smaller machines or in segments for larger machines & insulated from each other with varnish.
- The stamping also have openings which make axial and radial ventilation ducts to provide efficient cooling.
- Slots are provided on the inner periphery of the stator core.

→ These slots of 3 types.

(i) open type or wide open :-

→ The open slots are used because the coils can be form wound & insulated prior to being placed in the slots giving least expenditure and more satisfactory winding Method.




[Wide - open]

→ This type of slots also facilitates in removal & replacement of defective coils. But this type of slots have disadvantages of distributing the air gap flux in to branches or tufts which tends to produce ripples in the emf wave.

(ii) Semi - closed type :-

→ The semi closed type of slots are better in this respect but do not permit the use of form wound coils.



[Semi - closed]

④ Totally closed type :-

- Totally closed slots are rarely used because of its increased winding cost etc.



(Closed)

Stator winding / Armature winding :-

- The conductors placed in stator core slots & are connected in a particular fashion known as winding.
- The emf's are induced in the winding. It is usually made of insulated copper or aluminium wire.

⊕ Rotor :-


- The rotor is a rotating part of the alternator. It mainly used to house the magnetic poles & fixed winding.
- The field excitation is usually provided from a small DC shunt or compound generator known as an exciter mounted on the same shaft of the alternator.
- The exciting current is supplied to the rotor through two slip rings & brushes.
- The power rating of exciter is ordinarily 0.3 to 1% of power rating of the alternator.
- Based on construction, rotors are classified in to two types as follows.

Rotors

- Salient pole type (or) projection pole type Rotors (low speed, more numbers of poles, Kaplan turbines)
- Non salient pole type (or) smooth cylindrical type rotors (high speed (3000/1500 rpm), 2 or 4 poles, pelton wheel)

① Salient pole type rotor :-

- It is used in low & medium - Speed alternators.
- It poles are made of steel laminations rivetted together & are fixed to the rotor by a dove tail joint.
- The pole faces are usually provided with slots for damper winding (squirmel cage winding).
- The damper bars are short-circuited at both ends by copper rings.
- These dampers are used in preventing hunting & to provide starting torque in synchronous motor, field winding




(Salient pole type rotor)

- The field coils are placed on the pole-pieces as shown in figure and connected in series.
- The ends of the field windings are connected to a D.C. source through two slip-rings.
- The salient pole type structure has the following special features.
 - (i) They have large diameters and short axial length.
 - (ii) The pole shoes covers about 3 OF pole pitch.
 - (iii) Poles are laminated to reduce eddy current losses.
 - (iv) These are employed with hydraulic turbines or diesel engines.

Non - Salient pole or Smooth cylindrical type :-

- It is used in very high speed alternators usually driven by steam turbines also called turbo-alternators.



- The rotor consists of a smooth solid forged steel cylinder having a number of slots on its outer periphery for accommodating field winding such rotors are design mostly for 2-pole (or 4-pole) alternators running at 3000 r.p.m. (or 1500 r.p.m.).

- The unslotted portions from pole faces as shown in figure.
- General view of an assembly smooth cylindrical rotor is shown.
- The non-salient pole type structure has the following special features.
 - (i) They are small diameter and of very long axial length, (to reduce periphery velocity).
 - (ii) less windage losses.
 - (iii) High speeds are obtained i.e. 3000 r.p.m (or 1500 r.p.m)
 - (iv) Better in dynamic balancing and quieter in operation,

Slip rings :-

- usually hand drawn copper is used for manufacturing slip-rings.
- The circular slip rings are mounted on the same shaft and is insulated from the shaft.
- Slip rings facilitate the DC supply to the field winding through brushes.

Brush & Brush holder :-

- Brushes are made of carbon & are placed over the slip rings. It is a stationary part.
- Brush and brush holders are studied in D.C generators chapter, hence holds good here too.

SPIDER :-

- It is like hub on which magnetic poles are fitted and it is mounted on the shaft. It is made of either cast iron or cast steel.

EXCITER :-

- In alternators, the field winding is always required to be excited by a separate D.C. supply. Hence all the alternators are necessarily separately excited machines.
- This is achieved by providing a small D.C. generator called as an exciter mounted on the same shaft.

SHAFT & BEARINGS :-

- The shaft is made of cast steel. Its main function is to hold the rotor, slip rings & exciter in proper position. It is supported in bearings.
- Depending upon the rating and position of the shaft (horizontal or vertical) bearings, roller bearings or thrust bearings are used.

④ DIFFERENCE Betw salient pole & Non-salient pole rotor :-

salient pole

- Poles are projected.
- More number of poles are present.
- Large diameters ($\approx 10m$) & small axial lengths ($\approx 3m$).
- Used for low and medium speed.
- Motor windage losses.

Non Salient pole

- Outer surface is smooth. (Poles are not projected).
- Two or four poles are present.
- Small diameters ($\approx 1m$) & large axial lengths ($\approx 10m$).
- Used for high speeds. (turbo) (3000 rpm or 1500 rpm only)
- Less windage losses. (due to smooth surface).

Solient pole

- (vi) water turbines are preferred.
- vii) construction is difficult.
- viii) perfectly not balanced.
- ix) air gap is present in b/w poles
- x) flux is not uniform due to interpolar gap.

Non salient pole

- (vi) steam turbines are preferred
- vii) construction is easy.
- viii) perfectly balanced.
- ix) no air-gap in b/w poles.
- x) flux is uniformly distributed.

Advantages of stationary armature :-

- The following are the various advantages of alternator having stationary armature.
 - It is easy to insulate stationary winding.
 - Stator winding voltage rating can be increased.
 - It needs only 2 slip rings on D.C side.
 - Sparking at brushes is completely avoided.
 - Perfect mechanical balanced is obtained on stator winding.
 - It is easy to insulate slip-rings which are on D.C.
 - The rotor weight is less compared to stator weight.
 - They heavy bearings are not required since rotor is light weight.
 - Commutator is not present.

Alternator parts along with Material :-

- Table given below shows the various parts of alternator & material used for,

<u>Name of the parts</u>	<u>material used</u>
① Stator frame	Cast iron or cast steel
② Stator core	Silicon steel or sheet steel
③ Rotor core	Silicon steel
④ Stator & rotor winding	Copper
⑤ Insulation	Varnish, paper, etc.
⑥ Slip rings	Hard drawn copper.
⑦ Brushes	Carbon
⑧ shaft	Mild steel or carbon steel
⑨ End covers	forged steel.

—x—

3 phase winding in AC Machines


Armature winding :-

- Winding is an orderly arrangement of insulated conductors in the slots of armature / stator cores with their end connection in a specified sequence.
- Winding is mainly classified as
 - (i) closed coil winding.
 - (ii) open coil winding.

(i) closed coil winding :-

- It is also called D.C. armature winding, where in the coil ends are connected through the commutator segments to form the closed circuit.
- The end of the coil, after connecting through the other coils in the armature, finds its self connected to the commencement end of the starting


coil as shown in the figure.



(Closed coil winding)

⑥ Open coil winding :-

→ It is also called A.C stator winding.



(Open coil winding)


→ The end of the coil after connecting through others coils in the stator, is terminated as end lead, i.e., the starting end of the coil & the finishing end of the coil are kept on as shown in fig.

⑦ Conductors :-

→ The part of the wire which is under the influence of the magnetic field & responsible for the induced emf is called active length of the conductor. The conductors are placed in the armature slots.


Turn :-

- A conductor in one slot when connected to a conductor in another slot forms a turn. So two conductors constitute a turn. This is shown in fig.




Coil or winding element :-

- length of a wire lying in the magnetic field and in which an emf is induced is called an active conductor.
- Referring to fig, we find the two active conductors AB & CD along with their end connections constitute one coil or winding element of the armature winding.




[Coil or winding element]

→ The coil may consist of a single turn only as shown in below figure 3 or multi turns as shown.



- A single turn coil on winding element will have 2 conductors per coil side.
- In fig. for example, each coil side has 8 conductors.
- The group of conductors constituting a coil side of a multi-turn coil is tied together with a tape as a unit and is placed in the armature slot.
- There are as many commutator bars as the number of winding elements.



Active sides :-

- These are the sides which lie within the slots. They are also known as coil sides.
- The induction takes place only in the active sides of the coil while they move in the magnetic field.
- In winding calculation these active sides are considered as conductors.
- The coil has got two conductors irrespective of the number of turns.

Inactive sides :-

- That part of a coil which does not lies in the slot is known as coil sides.
- No induction takes place in the inactive coils.
- Ex :- Back and front end connections.

Leads of coil :-

- The ends coming out from a coil are known as leads of a coil. Every coil has got two leads.

pole pitch :-

- It is centre to centre distance between the two adjacent poles. We have seen that for one rotation of the conductors, 2 poles are responsible for 360° electrical of emf, 4 poles are responsible for 720° electrical of emf and so on. So 1 pole is responsible for 180° electrical of induced emf. So 180° electrical is also called one pole pitch.
- Practically how many slots are under one pole which are responsible for 180° electrical, are measured to specify the pole pitch.

→ Eg consider 2 pole, 18 slots armature of an alternator. Then under 1 pole there are $18/2$ i.e. 9 slots. So pole pitch is 9 slots. or 180° Electrical. This means 9 slots are responsible to produce a phase difference of 180° between the e.m.f.s induced in different conductors.

This number of slots/pole is denoted as 'n'

$$\therefore \text{Pole pitch} = 180^\circ \text{ electrical}$$

$$= \text{Slots/pole (no of slots/p.)}$$

$$= n$$

Slot angle (β) :-

- The phase difference contributed by one slot in degrees electrical is called slot angle β .
- As slots per pole contributes 180° electrical which is denoted as 'n', we can write,

$$\therefore 1 \text{ slot angle} = \frac{180}{n}$$

$$\therefore \beta = \frac{180}{n}$$


- In the above example,


$$n = \frac{18}{2} = 9$$

while,

$$\beta = \frac{180}{n} = 20^\circ$$

NOTE :-





→ This means that if we consider an induced emf in the conductors which are placed in the slots which are adjacent to each other, there will exist a phase difference of β° in betw them. While if emf induced in the conductors which are placed in slots which are 'n' slots distance away, there will exist a phase difference of 180° in between them.

—x—

(Types of 3 φ windings)


Types of armature windings :-

① Lap and wave winding :-

→ The armature windings are classified into two main groups , lap & wave windings.


Simple lap winding :-

→ In a simplex lap winding the end lead of coil 1 is connected to the begin lead of the adjacent (coil 2).




Simplex wave winding :-

- In simplex wave winding, the end lead of the coil 1 is connected to the beginning of a coil placed at a distance equal to one pole pitch.



Single layer winding :-

- A single layer winding is one in which only one coil side is placed in each armature slots as shown in fig. Such a winding is not used much.



Single layer winding

Two layer winding :-

- In this type of winding, there are two conductors on coil sides per slot arranged in two layers as shown in fig.




(Two-layer winding)

→ Usually, one side of every coils lies in the upper half of one slot & the other sides of the same coils lies in the lower half some i.e. other slot at a distance of one coil pitch away.

Multi-coil winding :-

- Some time 4 or 6 or 8 coil side are used in each slot in several layers because it is not practicable to have too many slots.
- The coil sides laying at the upper half of the slots are numbered odd, i.e., 1, 3, 5, 7 etc. while those at the lower half are numbered even i.e., 2, 4, 6, 8 etc.



Multi-Coil winding


Full pitch & short pitch winding :-

- As seen earlier, one pole pitch is 180° electrical.
- The value of 'n' slots per pole indicates how many slots are contributing 180° electrical phase difference.


- So if coil side is one slot is connected to a coil side in another slot which is one pole pitch distance away from first slot, the winding is said to be full pitch winding. and coil is called full pitch coil.
- for example in 2 pole, 18 slots another, the pole pitch is $n = \frac{18}{2} = 9$ slots. so its coil sides in slot no. 1 is connected to coil side in slot no. 10 such that two slots no. 1 & no. 10. are one pole pitch apart n slots or 180° electrical a part, the coil is called full pitch coil. Here we can define one more term related to a coil called coil span.

* Coil Span :-

- It is the distance on the periphery of the armature bet' two coil sides of a coil.
- It is usually expressed in terms of number of slots or 180° electrical the coil is called full pitch coil. This is shown in the fig.
- At against this if coils are used in such a way that coil span is slightly less than a pole pitch i.e less than 180° electrical, the coils are called short pitched coils or fractional pitched coils. Generally coils are shortened by one or two slots.



→ So in 18 slots 2 pole alternators instead of connecting a coil side in slot No. 1 to slots No. 10, it's connected to a coil sides in slot No 9 or slots no. 8 coil is said to be short pitched coil & winding is called short pitch winding. This is shown in fig.



Advantages of short pitch coil :-

- The length required for the end connections of coils is less. that is inactive length of winding is less. So, less copper is required. Hence economical.
- short pitching eliminates high frequency harmonics which distort the sinusoidal nature of emf. Hence wave form of an induced emf is more sinusoidal due to short pitching.
- As high frequency harmonics get eliminated, eddy current and hysteresis losses which depend on frequency also get minimised. This increases the efficiency.

Concentrated & distributed winding :-

- In three phase alternators, we have seen that there are 3 different sets of windings, each for a phase.
- So depending upon the total number of slots & number of poles, we have certain slots /phase available under each pole. This is denoted as 'm'.

$$\begin{aligned} m &= \text{Slots / pole / phase} \\ &= n / \text{number of phases} \\ &= n/2 \end{aligned}$$

for example in 18 Slots , 2 pole alternator we have,

$$n = \frac{18}{2} = 9$$

$$\& \quad m = \frac{9}{3} = 3$$


- So we have 3 slots /pole /phase available. Now let 'x' number of conductors /phase are to be placed under one pole, & we have 3 slots /pole /phase available.

- But if all 'x' conductors / phase are placed in one slot keeping remaining 2 slots / pole /phase empty then the winding is called concentrated winding. So in concentrated winding all conductors or coils belonging to a phase are placed in one slot under every pole.

- But in practice, an attempt is always made to use all the 'm' slots per pole per phase available for distribution of the winding.
- So, if 'x' conductors per phase are distributed amongst the 3 slots / phase available under every pole, the winding is called distributed winding.


Pitch factor or coil span factor (K_c) :-

- In actual practice, the winding used for the alternators is distributed and short pitch coil, hence emf induced slightly gets affected.
- Let us, see now the effect of short pitch type of winding on the emf equation.
- In case of short pitch, coil is formed by connecting one coil side to another which is less than one pole \times pitch away. So actual coil span is less than 180° .
- The coil is generally shorted by one or two slots.
- The angle by which coils are short pitched is called as angle of short pitch denoted as ' α '. This is shown in fig.




180° = full pitch
 $(180 - \alpha)$ = Short pitch

- when the coils are full pitched, the resultant emf in a coil is the algebraic sum of the emf induced in the 2 coil sides.
- while when the coils are short pitched, due to short pitch angle α ,
- the resultant emf in a coil is the vector sum of the emfs induced in the two coil sides.
- let E_s be the induced emf in each side of the coil.
- If the coil were full pitched i.e if its two sides were one pole-pitch apart, then total induced emf in the coil would have been = $2E_s$. as shown in fig.



(a) Algebraic sum (full pitched)



(b) Vector sum (short pitched)

(Algebraic sum (full pitched) and)
(Vector sum (short pitched))

- Now the algebraic sum is always more than the vector sum. So due to short pitching, the induced emf decreases by a factor called as coil span factor or pitch factor (K_p).
- It is defined as the ratio of resultant emf (E_R) when coil is short pitch to the resultant emf when coil is full pitched. It is always less than one.

$$K_c = \frac{ER \text{ when coil is short pitched}}{ER \text{ when coil is full pitched}}$$

from the above figure,

$$K_c = \frac{2E_s \cos\left(\frac{\alpha}{2}\right)}{2E_s}$$

$$K_c = \cos\left(\frac{\alpha}{2}\right)$$

where,

α = Angle of short pitch.


Note:- The value of α will usually be given in the problem, if not, then assume $K_c = 1$

④ Distribution of Breath factors or winding factors on spread factors :-

- It will be seen that on each phase, coil are not concentrated or bunched in one slot, but are distributed in a number of slots to form polar groups under each pole.
- These coils / phase are displaced from each other by a certain angle. The result is that the EMF's induced in the coil sides constituting a polar group are not in phase with each other but differ by an angle equal to angular displacement of slots.
- The following figure are shown the end connections of a 3-phase single layer winding for a 4-pole alternator. It has a total of 36 slots i.e., 9 slots / pole.

→ Obviously there are 3 slots / phase / pole.


for ex :- Coil 1, coils 2 & 3 being to R phase,




(Distribution factor)

→ Now these three coils which constitute one polar group are not bunched in one slot but in 3 different slots. Angular displacement betw any two adjacent slots = $180^\circ/9 = 20^\circ$ (electrical).

→ If 3 coils were bunched in one slot, then total emf induced in the three sides of the coil would be the arithmetic sum of the 3 emf's i.e., = $3E_s$, where E_s is the emf induced in one coil side.



→ Since the coil are distributed, the individual emf have a phase difference of 90° with each other. Their vector sum as seen from fig.



$$E = E_s \cos 20^\circ + E_s + E_s \cos 20^\circ$$

$$E = 2E_s \cos 20^\circ$$

$$E = 2E_s \times 0.9397 + E_s$$

$$E = 2.88 E_s$$

The distribution factor (K_d) is defined as

$$= \frac{\text{EMF with distributed winding}}{\text{Emf with concentrated winding}}$$

In the present case,

$$K_d = \frac{\text{EMF with winding in 3 slots / pole / phase}}{\text{EMF with winding in 1 slot / pole / phase}}$$

$$= \frac{E}{3E_s} = \frac{2.88 E_s}{3E_s} = 0.96$$

$$\therefore K_d = 0.96$$

General case :-

→ let β be the value of angular displacement betn the slots. Its value is


$$\beta = \frac{180}{\text{No of slots / pole}} = \frac{180^\circ}{n}$$

let $m = \text{No of slots / phase / pole}$.

$m\beta$ = phase spread angle.

→ Then the resultant voltage induced in one polar group would be mE_s , where E_s is the voltage induced in one coil sides.

→ The following figure illustrates the methods for finding the vector sum of m voltages each of value E_s & having a mutual phase difference of β .



$$AB = E_s = 2 \pi \sin \beta/2$$

$$\text{Arithmatic sum is } = mE_s = m \times 2 \pi \sin \beta/2$$

$$\text{The vector sum is } = AE = E_s = 2 \pi \sin m\beta/2$$

$$K_d = \frac{\text{Vector sum of coil e.m.f.s}}{\text{Arithmatic sum of coil e.m.f.s}}$$


$$K_d = \frac{2 \pi \sin m\beta/2}{m \times 2 \pi \sin \beta/2}$$

$$K_d = \frac{\sin m\beta/2}{m \sin \beta/2}$$

chording of winding :-

- Chording of the pole windings is one of the design factors.
- The 36-slots, four pole machine, an individual coil enters slot 1 & comes back in slot 10, it will be spanned 90 mechanical degrees of the stator circular structure.

- There are four poles, 90 mechanical degrees is 180 electrical degrees.
- The two sides of the coil are in the same relative position on the adjacent north & south pole positions. This is a full-pitch coil construction,



(Four-pole AC stator with full pitch coil)

- The more usual AC machine coil will cover less of the periphery of the machine and is then said to be fractional pitch.
- A typical situation might have a coil enter slot 1 & leave slot 7. This then covers six out of a possible nine slot pitches, & is a $6/9$ or 66.7% pitch.
- The majority of AC machine coils are of fractional pitch type.

ADVANTAGES OF FRACTIONAL PITCH WINDING :-

- The ends of the coil are shortened, which means less copper loss due to less total length.
- The end coils can be formed more compactly. The end belts will need less winding space resulting in a shorter unit.

- Improved wave form of the induced emf.
- fractional number of slots per pole can be used which in turn reduces tooth ripples.
- Mechanical strength of the coils is increased.
- the distinct reduction in machine harmonics due to cancellation of higher harmonics.
- All ac equipment is designed to operate on a pure sine wave , the generation of harmonics is to be avoided. This is especially so when the factor that achieves it is other wise desirable.

E.M.F Equation

Let,

Z_{ph} = Number of conductors on coil sides in series/ phase

$Z_{ph} = 2T_{ph}$, where T_{ph} is the number of coils on turns / phase.

P = number of poles

Φ = use full flux/pole , web on

N = Rotational speed of rotor , r.p.m

f = frequency , Hz

K_d = distribution factor

K_c = pitch factor or coil span factor

→ The alternator rotor move through one revolution in $t = \frac{60}{N}$ sec, the flux cut by the conductor
 $= P\Phi$ webers

The average emf induced in the conductor

$$E_{av} = \frac{d}{dt} (\text{flux}) \text{ volt}$$

$$= P \cdot \frac{\phi}{t}$$

$$= \frac{P\phi}{\frac{60}{N}}$$

$$\therefore E_{av} = \frac{P\phi N}{60}$$

We know that,

$$f = \frac{NsP}{120}$$

$$Ns = \frac{120f}{P}$$

Substituting the value of N in equation 1, we get

$$E_{av} = \frac{P\phi \times 120f}{60 \times P}$$

$$E_{av} = 2f\phi \text{ volt/conductor}$$

Average emf / phase

$$E_{av/\text{phase}} = 2f\phi \times 2T_{ph}$$

$$E_{av/\text{phase}} = 4f\phi T_{ph}$$

$$E_{rms/\text{phase}} = E_{av} \times \text{form factor}$$

$$E_{rms/\text{phase}} = 4f\phi T_{ph} \times 1.11$$

$$E_{rms/\text{phase}} = 4.44f\phi T_{ph} \text{ volt}$$

→ The above equation of emf induced / phase is true only.

→ The winding is concentrated in one slot but practically it is not true.

- the winding for each phase under each pole is distributed and for such cases K_c & K_d must be considered.
- Thus, emf induced /phase

$$E_{\text{rms}}/\text{Phase} = 4.44 f \phi T_{\text{ph}} K_c K_d \text{ Volt}$$

for full - pitched and concentrated winding.

$$K_p = 1 , K_d = 1$$

If the alternator is star-connected then the line voltage.


$$E_L = \sqrt{3} E_{\text{rms}} \text{ Phase}$$

$$E_L = \sqrt{3} \times 4.44 f \phi T_{\text{ph}} K_c K_d \text{ Volt}$$


shape of the Emf wave :-

- The instantaneous value of the induced emf in a conductor moving across the magnetic field is proportional to the rate of cutting the flux at that instant.
- The wave form of the induced emf is similar to the wave of the magnetic flux in the air-gap.
- When the distribution of the flux in the air gap is sinusoidal, the induced emf wave form will also be sinusoidal. But the flux wave form in practice is never exactly sinusoidal.
- Further harmonics do creep up due to various causes. The pulsating flux tufts at the armature teeth also cause harmonics.
- The following methods are employed to obtain emf wave whose shape is very close approximation to a sine wave.

→ The pole shoes are skewed. The field form due to a well designed skewed pole-shoe is shown in figure (b) while fig (a) shows a skewed pole.



(Fig - A)



(Field form)

- This method of obtaining a very good shape for the emf wave is simple & interesting, since the value of emf induced in a conductor is given by the expression.
- Since v (velocity) is assumed to be constant, either B (flux density) or I (active length of conductor) must vary according to a sine law. How the active length I varies is shown fig (a).
- As the conductor moves relative to the poles, the length of conductor under the influence of a pole varies over a certain distance from instant to instant.
- The pole-shoes should be given such a shape that the variation of the length I is according to a sine law.
- The flux density under the gap can be made to vary according to a sine law if the gap length

varies from the centre of the pole to the tips of the pole-shoes.

- The increase in the gap length is made almost twice and the ratio $\frac{\text{Pole arc}}{\text{pole pitch}}$ is kept round about 0.67.
- In turbo-alternators, where rotor is cylindrical in form the unslotted portion should be 0.3 times the pole pitch.
- The field windings are accommodated in several points of slots, the windings of each pair contribute towards the total mmf.
- The result gap density approaches very near to a sine wave law.
- Problems - 1 :-

A 3Φ, 16 pole alternator has a star-connected winding with 144 slots & the conductors per slot. The flux per pole is 0.03 wb. sinusoidally distributed and the speed is 375 rpm. Find the frequency, phase & line voltages. Assume full-pitched coils.

Soln :-

Given Data,

$$\text{No of poles (P)} = 16$$

$$\text{Synchronous speed (N_s)} = 375 \text{ rpm}$$

$$\text{Flux/pole} (\Phi) = 0.03 \text{ wb}$$

$$\text{Number of slots} = 144$$

$$\text{Conductors/slots} = 10$$

$$\text{full pitched coil (K_c)} = 1$$

To find,

frequency (f) = ?

phase voltage (E_{ph}) = ?

line voltage (E_L) = ?

Formula used,

$$\text{frequency } (f) = \frac{N_s P}{120}$$

$$\text{slot/pole } (n) = \frac{\text{Slot}}{\text{pole}}$$

$$\text{slot angle } (\beta) = \frac{180^\circ}{n}$$

$$m = \text{slot/pole/phase}$$

$$\text{Distribution factor } (K_d) = \frac{\sin \left(\frac{m\beta}{2} \right)}{m \sin \left(\frac{\beta}{2} \right)}$$

No of conductors (Z) = slots \times conductor / slots

Total number of turns / phase (T_{ph}) = $\frac{Z_{ph}}{2}$

Phase voltage (E_{ph}) = $4.44 K_c K_d f \phi T_{ph}$

Line voltage (E_L) = $\sqrt{3} E_{ph}$

SOL

$$\text{frequency } (f) = \frac{P N_s}{120}$$

$$= \frac{16 \times 375}{120} = 50 \text{ Hz}$$

$$\text{slot/pole } (n) = \frac{144}{6} = 9$$

$$\text{slot angle } (\beta) = \frac{180}{n} = \frac{180}{9} = 20^\circ$$

$$m = \frac{144}{16 \times 3} = 3$$

$$\text{Distribution factor } (K_d) = \frac{\sin 3 \left(\frac{20}{2} \right)^{10}}{3 \sin \frac{20}{2}^{10}}$$

$$K_d = 0.966$$

$$Z_{ph} = 144 \times \frac{10}{3} = 480$$

$$T = \frac{480}{2} = 240$$

full pitch winding (K_c) = 1

$$E_{ph} = 4.44 \times 1 \times 0.96 \times 50 \times 0.03 \times 240$$

$$E_{ph} = 1534 \text{ V}$$

line voltage, $E_L = \sqrt{3} E_{ph}$

$$E_L = \sqrt{3} \times 1534$$

$$E_L = 2658 \text{ V.}$$

\therefore frequency (f) = 50 Hz

phase voltage (E_{ph}) = 1534 V

line voltage (E_L) = 2658 V.

Problem - 2 :-

- A 3Φ, star connected alternator has the following data; voltage required to be generated on open-circuit = 4000 V (at 50 Hz), speed = 500 RPM, stator slots/pole / phase = 3 conductors / slots = 12, calculate
(i) Number of poles
(ii) useful flux/poles
Assume all conductors / phase to be connected in series & coil to be full pitch.

Given Data,

Generated open ckt voltage (E_L) = 4000V

Synchronous speed (N_s) = 500 rpm

Conductors / slot = 12

Stator slots / pole / phase (m) = 3

frequency (f) = 50 Hz

To find

Number of poles (P) = ?

Flux / pole (Φ) = ?

Formula used

$$P = \frac{120f}{N_s}$$

$$\Phi = \frac{Eph}{4.44 f T_{ph} K_c K_d}$$

Solution

$$\therefore P = \frac{120f}{N} = \frac{120 \times 50}{1500}$$

$$= 12 \text{ poles}$$

Pitch factor or coil span factor

$$K_c = 1$$

$$m = 3$$

No. of slots/pole (n) = $3 \times 3 = 9$

Angular displacement betn slots (β) = $\frac{180}{n}$

$$= \frac{180}{9}$$

$$= 20$$

$$\therefore K_d = \frac{\sin \frac{m\beta}{2}}{m \sin \frac{\beta}{2}}$$

$$\Rightarrow \frac{\sin \left(\frac{3 \times 20}{2} \right)^{\circ}}{3 \sin \frac{20}{2}^{\circ}} = \frac{\sin 30^{\circ}}{3 \sin 10^{\circ}} = 0.96$$

Number of turns / phase

$$T_{ph} = \frac{2P_h}{2}$$

$$\therefore 2P_h = \frac{2}{3} = \frac{12 \times 9 \times 12}{3}$$

$$\therefore T_{ph} = \frac{12 \times 9 \times 12}{3 \times 2}$$

$$= 216$$

Now using the relative,

$$E_{ph} = 4.44 \Phi T_{ph} K_p K_d \text{ Volts}$$

$$2309 = 4.44 \times 50 \times \Phi \times 216 \times 1 \times 0.96$$

$$\Phi = \frac{2309}{4.44 \times 50 \times 216 \times 1 \times 0.96}$$

$$= 0.05 \text{ wb}$$

\therefore No. of poles (P) = 12 poles

$$\text{flux/pole } (\Phi) = 0.05 \text{ wb}$$

problem - 3 :-

A 3ϕ , 10 pole alternator has 2 slots / pole / phase on its stator with 10 conductors / slot. The air gap flux is sinusoidally distributed & equals to 0.05 wb . The stator has double layer winding with a coil span of 150° electrical degrees. If the alternator is running at 600 rpm, calculate the emf generated / phase at no load.

Given Data :-

Number of poles (P) = 10

slots / pole / phase (m) = 2

conductors / slot (= 10)

coil span = 150° (Electrical)

speed (N) \geq 600 rpm

To find

Emf generated / phase at no load (E_{ph}) \approx ?

formula used

phase voltage (E_{ph}) \approx $4.44 K_c K_d F \Phi T_{ph}$

solution

$$\text{No of slots/pole (n)} = 2 \times 3 = 6$$

Angular displacement bet' the slots

$$(\beta) = \frac{180}{n} = \frac{180}{6} = 30^\circ$$

$$\text{Angle of chording } (\alpha) = 180^\circ - 150^\circ \\ = 30^\circ$$

$$\therefore K_c = \cos \frac{\alpha}{2} \\ = \cos \frac{30}{2} = \cos 15^\circ \\ = 0.9659$$

$$\therefore K_d = \frac{\sin \left(\frac{q\beta}{2} \right)}{q \sin \left(\frac{\beta}{2} \right)} = \frac{\sin \frac{2 \times 30}{2}}{2 \sin \frac{30}{2}} \\ = 0.9659$$

Number of conductors in series / phase

$$Z_{ph} = 10 \times \text{slots / phase} \\ = 10 \times (2 \times 10) \\ = 200$$

$$\text{Number of turns / phase } T_{ph} = \frac{Z_{ph}}{2}$$

$$= \frac{200}{2} = 100$$

$$\therefore E_{ph} = 4.44 \times F \Phi T_{ph} K_c K_d \\ = 4.44 \times 50 \times 0.05 \times 100 \times 0.9659 \times 0.9659 \\ = 1035.6 \text{ V}$$

 (Ans)

Problem - 4 :-

calculate the speed & open - ckt lines & phases voltages of a 4-pole , 3 phase , 50 Hz , star connected alternator with 36 slots & 30 conductors /slots . The flux /pole is 0.05 wb sinusoidally distributed.

Given data

$$\text{No}^{\circ} \text{ of poles } (P) = 4$$

$$\text{frequency } (f) = 50 \text{ Hz}$$

$$\text{No}^{\circ} \text{ of slots} = 36$$

$$\text{No}^{\circ} \text{ of conductor/slot} = 30$$

$$\text{flux per/pole } (\Phi) = 0.05 \text{ wb.}$$

To find

$$\text{Speed of alternator } (N_s) = ?$$

$$\text{Open ckt line voltage } (E_L) = ?$$

$$\text{open ckt phase voltage } (E_{ph}) = ?$$

formula used

$$\text{Speed } (N_s) = \frac{120f}{P}$$

$$\text{Phase voltage } (E_{ph}) = 4.44 f \Phi K_c K_d T_{ph}$$

Solution

$$N_s = \frac{120f}{P} = \frac{120 \times 50}{4}$$

$$= 1500 \text{ rpm}$$

Number of conductors connected in series /phase

$$Z_{ph} = \frac{\text{No}^{\circ} \text{ of slots} \times \text{No. of conductors/slots}}{\text{No. of phases}}$$

$$= \frac{36 \times 30}{3}$$

$$= 360$$

$$\text{No. of turns /phase (T}_{ph}\text{)} = \frac{\frac{2}{2} ph}{2}$$

$$= \frac{360}{2}$$

$$= 180^\circ$$

$$\text{No. of slots /pole} = n = \frac{36}{4}$$

$$= 9$$

$$\text{No. of slots /pole/ phase (m)} = \frac{9}{3} = 3$$

Angular displacement betn the slots

$$(\beta) = \frac{180}{n} = \frac{180}{9} = 20$$

$$\therefore K_d = \frac{\sin \frac{3 \times 20}{2}}{3 \sin \frac{20}{2}} = \frac{\sin 30}{3 \sin 10}$$

$$= 0.96$$

$$\text{pitch factor (K}_c\text{)} = 1$$

open ckt phase voltage (E_{ph})

$$= 4.44 \times 50 \times 0.05 \times 180 \times 1 \times 0.96$$

$$= 1918.1 \text{ V}$$

$$\text{open ckt line voltage (E}_L\text{)} = \sqrt{3} E_{ph}$$

$$= \sqrt{3} \times 1918.1$$

$$= 3322.2 \text{ V.}$$

\therefore speed of alternator (N) = 1500 rpm.

$$\text{open ckt phase voltage (E}_{ph}\text{)} = 1918.1 \text{ V.}$$

$$\text{open ckt line voltage (E}_L\text{)} = 3322.2 \text{ V.}$$

Problem-5 :-

- A 3Φ, 8 pole, 50 Hz, star connected alternator has 96 slots with 4 conductors / slot. The coil pitch is 10 slots. If the flux / pole is 6 mwb, find.
- The phase voltage
 - The line voltage
 - If each phase carrying 650 A, what is the kVA rating of the machine?
 - If each phase carrying 650A,

Given Data :-

$$P = 8 \text{ poles}$$

$$F = 50 \text{ Hz}$$

$$\Phi = 60 \text{ mwb.}$$

$$\text{coil pitch} = 10 \text{ slots}$$

$$\text{No of slots} = 96$$

Solution

$$(n) = \text{slots/pole} = \frac{96}{8} = 12$$

$$\text{slots angle} (\beta) = \frac{180^\circ}{12} = 15^\circ$$

$$(m) \text{ slots/pole/phase} = \frac{12}{3} = 4$$

$$\text{coil pitch} = 10 \text{ slots}$$

$$= 10 \times \beta$$

$$= 10 \times 15$$

$\Rightarrow 150^\circ$ electrical

\therefore Angle of short pitch

$$(\alpha) = 180^\circ - 50^\circ$$

$$= 30^\circ$$

$$\therefore K_C = \frac{\cos \alpha}{2} = \cos 15^\circ = 0.9659$$

$$\therefore K_d = \frac{\sin \left(\frac{m\beta}{2} \right)}{m \sin \frac{\beta}{2}} = \frac{\sin \frac{4 \times 15}{2}}{4 \sin \frac{15}{2}}$$

$$= \frac{\sin 30}{4 \sin \frac{15}{2}}$$

$$= 0.9576$$

Total number of conductors

$$= \text{number of slots} \times \text{conductors/slot}$$

$$= 96 \times 4$$

$$= 384$$

$$\therefore \text{Total turns} = \frac{384}{2} = 192$$

$$\therefore T_{ph} = \frac{192}{3} = 64$$

(i) The phase voltage =

$$E_{ph} = 4.44 Kc K_d \Phi f T_{ph}$$

$$= 4.44 \times 0.9659 \times 0.9576 \times 60 \times 50 \times 64$$

$$= 788.497 \text{ V.}$$

(ii) The line voltage

$$E_{line} = \sqrt{3} E_{ph} = \sqrt{3} \times 788.497$$

$$= 1365.71 \text{ V.}$$

(iii) KVA Rating

$$I_L = 650 \text{ A} = I_{ph} \text{ (Star connected)}$$

$$\therefore \text{KVA rating} = \sqrt{3} \times E_{line} \times I_L$$

$$= \sqrt{3} \times 1365.71 \times 650$$

$$= 1537.56 \text{ kVA.}$$

Problem - 6 :-

A single phase 1500 r.p.m., 4 pole alternator has 8 conductors / slot with total of 24 slots. The winding is short pitched by $\frac{1}{6}$ th of full pitch. Assume distributed winding with flux / pole as 0.05 wb, calculate the induced emf.

Given data :-

$$N_s = 1500$$

$$P = 4$$

$$\text{Slots} = 24$$

$$\text{Conductors / slot} = 8$$

Solution :-

Note that the alternator is single phase & not the 3 ϕ

$$f = \frac{PN_s}{120} = \frac{4 \times 1500}{120} = 50 \text{ Hz}$$

$$n = \frac{\text{Slots}}{\text{pole}} = \frac{24}{4} = 6$$

$m = n = 6$ as number of phases in one

$$\beta = \frac{180}{n} = \frac{180}{6} = 30^\circ$$

$$\therefore K_d = \frac{\sin\left(\frac{6 \times 30}{2}\right)}{6 \sin\left(\frac{30}{2}\right)} = 0.6439$$

full pitch $\approx (n) = 6$ slots

coil short pitched by $\frac{1}{6}$ th of full pitch i.e,
by $\frac{1}{6} \times 6 = 1$ slots.

Angle of short pitch = 1 slot angle

$$\alpha = \beta = 30^\circ$$

$$K_c = \cos\left(\frac{\alpha}{2}\right) = \cos\left(\frac{30}{2}\right)$$
$$= \cos 15 = 0.9659$$

Total conductors = $\frac{\text{conductors}}{\text{slot}} \times \text{slots}$

$$Z = 8 \times 24 = 192$$

But as number of phase = 1, $Z = Z_{ph} = 19$

$$\therefore T_{ph} > \frac{Z_{ph}}{2} = \frac{192}{2} = 96 \quad [\because 2 \text{ conductors : } 1 \text{ turn}]$$

$$\therefore E_{ph} = 4.44 K_c K_a \Phi + T_{ph}$$
$$= 4.44 \times 0.9659 \times 0.6438 \times 0.05 \times 50 \times 96$$
$$= 662.74 \text{ V}$$
$$= \text{(Ans)}$$

ARMATURE REACTION & ITS EFFECT

ON EMF AT DIFFERENT POWER FACTOR OF LOAD

Definition excitation :-

- The field structure is the rotor & the DC voltage applied to the windings on the field rotors to produce magnetic flux is turned as the excitation.

Exciter :-


- In A.C generators, D.C. supply to excite the magnetic poles provided on the rotor.
- The magnetic poles become power full electromagnets and establish magnetic flux between rotor pole shoe & stator core. This D.C supply is obtained usually from a D.C generator known as exciter.

Types of exciter :-

- The excitors can be classified by 3 types namely,
 - (a) Main exciter
 - (b) pilot excitor
 - (c) static exciter

(a) Main exciter :-

- In operation an alternator requires its field current to be varied & this is usually obtained by varying the dc voltage of the main exciter.
- This is turn, is obtained by varying the field current of main exciter. The location of exciter is shown in figure.



(b) Pilot exciter :-

→ When the main exciter capacity is itself quite large variation of field current is obtained by changing the field current of a 'pilot exciter', whose armature supplies the field of the main exciter.

(c) Static excitation :-

- Now a days D.C is produced by using electronic rectifiers rather than DC rotating machines.
- The main exciter is replaced by a 3-phase AC generator with a stationary D.C field.
- This generator usually generates an A.C voltage which is converted to D.C by a 3-phase bridge rectifier & then supplied to the rotor D.C field of the main alternator.
- The exciting generator and rectifiers mounted on the main shaft & turn along with the rotor need of slip rings & brushes. Hence there is no
- The D.C excitation for the excitation generator is supplied by a pilot exciter which could be a rectified A.C. source.

Needs Of exciter :-

- In alternators, the field winding is always required to be excited by a separate D.C. supply. Hence the alternators are necessarily separately excited machines.
- This is achieved by providing a small D.C. generator called as an exciter mounted on the same shaft.
- This produces the required D.C. voltage of the order of 110 V. to 250 V., when alternator is driven by the prime mover.
- This voltage is given to the field winding with the help of slip rings mounted on the same shaft between alternator & generator.

Armature reaction of alternators on load at various power factors :-


- The armature winding of an alternator carries current only when the alternator is loaded.
- At no load, there will be no current flowing through the armature winding.
- If alternators under loaded condition, there are two fluxes present in the air gap.
- There are,
 - Flux due to the field ampere turns
 - Flux due to the current flowing through the armature winding.
- There is already another flux due to field current, that is also present in the air gap.
- Now there are two fluxes present in the air gap.

But actually the machine need only the fluxes due to field ampere turns only.


- The effect of armature flux due to armature current over the main field flux is called armature reaction.
- When the armature carries the load current, a armature flux (Φ_a) is produced in the armature winding and is also present in the air gap.
- This effect can be in the following forms.
 - There are
 - The armature flux will produce a distortion over the field flux.
 - The armature flux will oppose the main field flux (on) will help the main field flux.

Powers factors :-

- ① Unity power factor :-
 - These punches are used to make witness marks on scribed lines.
 - The armature flux is cross magnetizing.
 - The result is that the flux (MMF waves) at the leading tips at the poles is reduced while at the trailing tips it is increased.
 - The two effects nearly offset each other, leaving the average field strength increased.
 - The armature reaction for unity power factor is distortional.




② zero power factor lagging :-




Zero P.F. lagging

- The armature flux is in direct opposition to the main flux.
 - The main flux is decreased.
 - The armature reaction in this case is wholly demagnetising, with the result that due to the weakening of the main flux, less emf is generated and hence the armature / output voltage will be lower.
 - To maintain the value of the generated emf / output voltage, at the desired level.
 - The field excitation current will have to be increased to compensate for this weakening of the main flux.
- ③ zero power factor leading :-
- The armature flux wave has moved forward by 90° , so that it is in phase with the main flux wave. This results an increased or added main flux.



- The armature reaction is wholly magnetising, which results in greater induced emf and the armature / output voltage will be higher.
- To maintain the generated emf / output voltage at the design level, the field excitation current will have to be reduced.

④ Other power factors lagging :-



- The effect is partly distortionary and partly demagnetizing for other loads having lagging power factors of intermediate values.
- Most load fall in this category in actual usage.


Alternator overload :-

- The alternator load is varied, its terminal voltage 'V' is also found to vary as in D.C generators. This variation in terminal voltage 'V' is due to the following reason,

- ④ Voltage drop due to armature resistance R_a ,
 - ⑤ Voltage drop due to leakage reactance X_L .
 - ⑥ Voltage drop due to armature reaction.
- Armature resistance / phase R_a , causes a voltage drop / phase of $I R_a$, which is in phase with armature current I .
- The voltage drop is practically negligible because R_a is very low resistance.


⑦ Armature leakage reactance :-

- When current flows through the armature conductors, fluxes are set up which do not cross the air gap, but take different paths. Such fluxes are known as leakage flux.



- The leakage flux is practically independent of saturation, but is dependent on I & its phase angle with the terminal voltage V .
- The leakage flux sets up an emf of self inductance which is known as reactance emf & which is ahead of I by 90°.

→ The armature winding is assumed to possess leakage reactance, X_L .



Vector diagram

→ A part of the generated emf is used up in overcoming this reactance emf = $I X_L$

$$E = V + I (R_a + jX_L)$$

θ = The angle of twist (radian s)

④ SYNCHRONOUS REACTANCE :-

→ The terminal voltage is decreased from its no load value E_0 to V (for a lagging power factor). This is because of

- Voltage drop due to armature resistance = $I R_a$
- Voltage drop due to leakage reactance = $I X_L$
- Voltage drop due to armature reaction = $I X_a$

→ The voltage drop due to armature reaction may be accounted for by assuming the presence of a fictitious reactance X_a in the armature winding.

→ The value of X_a is such that $I X_a$ represents the voltage drop due to armature reaction.

→ the leakage reactance X_L (or X_p) & the armature X_a may be combined to give synchronous reactance X_s .

→ Hence $X_s = X_L + X_a$

→ the ohmic value of X_a varies with the power factor, because armature reaction depends on the load power factor.

→ Therefore total voltage drop in an alternator on load is


$$\begin{aligned} = I R_a + j I X_s &= I (R_a + j X_s) \\ &= I X_s \\ &= I Z_s \end{aligned}$$

where,

Z_s is known as the synchronous impedance of the armature.

→ The word "synchronous" is used merely as an indication that it refers to the working conditions.

→ The vector difference between "No load" voltage E_0 & output / terminal voltage V is equal to $I Z_s$ as shown figure.



SYNCHRONOUS IMPEDANCE :-

→ Synchronous impedance may be defined as the vector sum of the armature resistance and synchronous reactance.

$$\rightarrow Z_s = \sqrt{R_a^2 + X_s^2}$$

Effect of synchronous impedance :-

- Depending on load, synchronous impedance voltage drop is added vectorially to terminal voltage to get No load EMF.
- Its impact is to change the excitation to the alternator.

Load conditions:-

(a) Purely resistive load :-

- Current is in phase with voltage.
- The armature reaction is to distort the main field.
- Hence excitation remains unchanged.

(b) Purely inductive load :-


- Current lags by 90° behind the voltage.
- The armature reaction is to demagnetize the main field.
- Hence excitation has to be increased.

(c) pure capacitive load :-

- current leads by 90° ahead the voltage.
- the armature reaction tries to magnetize the main field.
- hence excitation has to be decreased.

Reasons for Voltage Variation on-load :-

- The D.C. generators, we have seen that due to the armature resistance drop and brush drop it is not possible to have all the induced emf available across the load.
- The voltage available to the load is called as terminal voltage.
- The concept is same in case of alternators.




- The entire induced emf cannot be made available to the load due to the various internal voltage drops.
- So the voltage available to the load is called as terminal voltage denoted as V_{ph} .
- In case of 3-phase alternators as all the phases are identical, the equations & the phasor diagrams are expressed on per phase basis.

- So if E_{ph} is the induced emf /phase in the alternator, there are following voltage drops occurs in an alternator.
- The drop across the armature resistance, $I_a R_a$ (both I_a & R_a are per phase values)
- The drop across synchronous resistance, $I_a X_s$ (both I_a & X_s are per phase values)
- After supplying these drops, the remaining voltage of E_{ph} is available as the terminal voltage V_{ph} .
- Now drop $I_a R_a$ is always in phase with I_a due to a resistive drop while current I_a lags by 90° with respect to drop $I_a X_s$ as it is drop across purely inductive reactance.
- All these quantities can not be added or subtracted algebraically but must be added or subtracted vectorially, considering their individual phases. But we can write a voltage equation in its phasor form as,
- $\bar{E}_{ph} = \bar{V}_{ph} + \bar{I}_a R_a + \bar{I}_a X_s$
- This is called as voltage equation of an alternator. The circuit form this is as shown in figure.

Worked example :-

→ A 3-Φ star-connected alternator supplies a load of 10 MW at P.F. 0.85 lagging and at 11 KV. Its resistance is 0.1 Ω per phase & synchronous reactance 0.66 Ω per phase. Calculate the line value of emf generated.



Circuit diagram

Solution :-

$$\text{F.L output current} = \frac{10 \times 10^6}{\sqrt{3 \times 11000 \times 0.85}} \\ = 618 \text{ A}$$

$$\text{T.Ra drop} = 618 \times 0.1 \\ = 61.8 \text{ V}$$

$$\text{T.Xs drop} = 618 \times 0.66 \\ = 408 \text{ V}$$

$$\text{terminal voltage}/\text{phase} = \frac{11000}{\sqrt{3}}$$


$$= 6350 \text{ V.}$$

$$\phi = \cos^{-1}(0.85)$$

$$\Rightarrow \phi = 31.8^\circ$$

$$\Rightarrow \sin \phi = 0.527$$

As seen from the vector diagram of where \mathbf{I} instead of \mathbf{V} has been taken along reference vectors.



$$\begin{aligned}\mathbf{E}_0 &= \sqrt{(V \cos \phi + I R_a)^2 + (V \sin \phi + I a_X)^2} \\ &= \sqrt{(6350 \times 0.85 \times 61.8)^2 + (6350 + 0.527 + 408)^2} \\ &= 6625 \text{ V}\end{aligned}$$

$$\text{line em.f} = \sqrt{3 \times 6625} = 11486 \text{ Volt}$$

Vector diagram of alternators on load :-
(for lag, lead & unity power factor)

Let,

E_0 = No load emf / phase

V = Terminal voltage / phase

I = Load current / phase

Z_s = Synchronous impedance / phase

X_a = fictitious reactance due to the armature reaction.


R_a = Effective armature resistance / phase

X_L = leakage reactance / phase

X_S = Synchronous reactance / phase

① Vector diagram for lagging power factor :-


(Inductive load) :-



→ The voltage drop due to armature reaction is equal to the voltage drop on fictitious reactance X_a . All the values are referenced to phase values.

- The phasor diagram for lagging power factor, unity power factor (pure resistive) & leading power factor (capacitive).


② Vector diagram for unity power factor :-



- In all the vector diagrams, the voltage taken as reference vector.
- For unity power factor load, the voltage (V) is in phase with the load current (I) as shown in figure.
- For lagging power factor load (I) lags the voltage by an angle θ shown in figure.
- For leading power factor load, the load current (I) leads from the voltage by an θ angle shown in fig.

③ vector diagram for leading power factor :-

- In all the vector diagrams due to armature effective resistance IR_a the voltage drop will be in phase with the current I .



- The voltage drop due to leakage reactance X_L & the voltage drop due to armature reaction Ix_a ; will be in quadrature (90°) with the load current I .
- The NO load voltage E_0 is the vector sum of terminal voltage (V) & sum of above voltage drops i.e Iz_s .

where

z_s is the synchronous impedance

$$\begin{aligned} \text{Total voltage drop on load} &= IR_a + j(Ix_L + Ix_a) \\ &= I[R_a + j(x_L + x_a)] \end{aligned}$$

$$\text{Total voltage drop on load} = Iz_s$$

$$\therefore \text{Voltage on NO Load } E_0 = \bar{V} + \bar{I}z_s$$

Voltage Regulation


Voltage regulation :-

- The voltage regulation of an alternator is defined as the rise in voltage when full load is removed divided by the rated terminal output voltage.

% regulation ('up')

$$= \frac{E_0 - V}{V} \times 100$$

- $E_0 - V$ is the arithmetical difference & not the vectorial one.
- The leading load pf, terminal voltage will fall on removing the full load. Hence regulation is negative in that case.
- The rise in voltage when full load is thrown off is not the same the fall in voltage when full load is applied.
- Voltage characteristics of an alternator are shown in figure,



Voltage Regulation Curve

Determination of voltage regulation :-

- The regulation may be found out by direct loading & the procedure is as follows :
- The terminal voltage is adjusted to its rated value 'V'.
- The load is varied until the watt meters and ammeters indicate the rated values at the desired power factor.
- The entire load thrown off while the speed & field excitation are kept constant.
- The open circuit or no load voltage E_0 is read.
Now regulation can be found from.

$$\% \text{ regulation} = \frac{E_0 - V}{V} \times 100$$

- The large machines, the costs for finding the regulation by direct loading as for small machines becomes prohibitive.
- It will be found that all these methods differ chiefly in the way the no load voltage E_0 is found in each case.

Regulation for large machines :-

- The following methods are used for determination of regulation for large machines.
 - ④ Synchronous impedance or EMF Method. The method is due to the pioneering work by Behn eschenburg.
 - ④ The ampere turn or mmf method. This method is the contribution by Rotherit.
 - ④ Zero power factor or potier method. This method is the work alone by potier.

Parameters Required :-


- All the methods to determine the regulation for large machines require the following parameters of the machine/ alternator.
- These are,
 - ④ Armature (or stator) resistance.
 - ④ Open circuit/no load characteristics
 - ④ short circuit characteristics

EMF method or Alternator test :-

- To determine the regulation of an alternator, the following tests are performed.
 - (a) open - circuit test.
 - (b) short - circuit test.


(a) Open - circuit test :-

→ The machine is run on no-load & the induced emf per phase is measured corresponding to various values of field current & a curve is drawn between induced emf per phase E_{ph} & field current I_F as shown in figure.



(b) short - circuit test :-


- In this test armature winding is short-circuited through a low resistance ammeter 'A' is shown.
- During this test the speed is kept constant & short-circuit current is measured corresponding to various values of field current.
- The excitation is increased so as to give 1.5 to 2 times the value of the full-load current.




→ The short circuit characteristics is a curve drawn between short-circuit current I_{sc} & field current I_f as shown in figure.

Synchronous impedance method :-

- The following procedural steps are involved in this method.
- The open circuit characteristics is plotted from given data as shown in figure.
- The short circuit characteristics curve is drawn from the data of the short circuit test. It is a straight line passing through the origin.



Characteristic Curve



Vector diagram

- Both these curves as drawn on a common field current base.
- Consider a field current I_F .
- The open circuit (OC) voltage for this field current is E_1 .
- When the winding is short circuited, the terminal voltage is zero. Hence it may be assumed that the whole of this voltage E_1 is being used to circulate the armature short circuited current I_s , against the synchronous impedance Z_s .

Therefore,

$$E_1 = I_s Z_s$$

Where,

$$Z_s = \frac{E_1 \text{ (open ckt)}}{I_s \text{ (short ckt)}}$$

- R_a can be found as discussed earlier,

$$X_s = \sqrt{Z_s^2 - R_a^2}$$

- R_a & X_s are known, vector diagram shown in fig can be drawn for any load and any power factor.

- Vector diagram $OD = E_0$,

$$\begin{aligned} \therefore E_0 &= \sqrt{OB^2 + BD^2} \\ &= \sqrt{(V\cos\phi + IR_a)^2 + (V\sin\phi + IX_s)^2} \end{aligned}$$

$$\text{Therefore \% regulation} = \frac{E_0 - V}{V} \times 100$$


- The value of regulation for unity power factor or leading power factors can also be found out in a similar way.
- Note that this method of determining the voltage regulation has the following limitations.
 - This method is not very accurate because the value of Z_s so found is always more than its value under normal voltage condition & saturation. Hence the value of regulation so found is always more than that found from an actual test. That is why this is called "Pessimistic method".
 - This value of Z_s is not constant but varies with "saturation" at low saturation its value is larger, because then the effect of a given armature ampere - turns is much more than at high saturation.
- Now under short circuit condition, saturation is very low, because armature mmf is directly demagnetizing.
- Different values of Z_s , corresponding to different values of field current are also plotted in figure.
- The value of Z_s usually taken is that obtained from full load current in the short circuit test.


→ In this method, armature reactance, X_s has not been treated separately but along with leakage Reactance X_L .

Worked example using synchronous method/ EMF Method. :-

- From the following test results, determine the voltage regulation of a 200 - V . 1 phases alternator delivering a current of 100 A at (i) unity p.f
 (ii) 0.8 lagging p.f
 (iii) 0.71 lagging p.f

Test results → Full-load current of 100 A is produced on short-circuit by a field excitation of 2.5 A, An emf of 500 V is produced on open-circuit by the same excitation. The armature resistance is 0.8Ω .





Solution

$$\text{For same excitation } Z_s = \frac{\text{O.C. Voltage}}{\text{S.C. Current}}$$

$$= 500 / 100$$

$$= 5 \Omega$$

$$X_s = \sqrt{Z_s^2 - R_a^2}$$

$$= \sqrt{5^2 - 0.8^2}$$

$$= 4.936 \Omega$$

Unity P.F. :-

$$I R_a = 100 \times 0.8$$

$$= 80 \text{ V};$$


$$I X_s = 100 \times 4.936$$

$$= 494 \text{ V}$$

$$E_0 = \sqrt{(2000 + 80)^2 + 494^2} = 2140 \text{ V}$$


$$\% \text{ Regulation} = \frac{2140 - 2000}{200} \times 100$$

$$= 7\%$$



(Unity Power factor) out

- P.F = 0.8 (lead)



(Power factor at 0.8 leading)


$$E_o = \left[(2000 \times 0.8 + 80)^2 + (2000 \times 0.6 - 494)^2 \right]^{\frac{1}{2}}$$

$$= 1820 \text{ V}$$

$$\% \text{ regulation} = \frac{1820 - 2000}{2000} \times 100$$

- P.F = 0.71 (lag)

$$= -9\%$$



(Power factor at 0.71 lagging)

$$E_0 = \left[(2000 \times 7.1 + 80) + (2000 \times 0.71 - 494) \right]^2$$

$$= 2432 \text{ V}$$

$$\% \text{ regulation} = \frac{2432 - 2000}{2000} \times 100$$

$$= 21.6 \%$$


— X —

Vector diagram & regulation for lagging, leading & unity power factor load

(a) Vector diagram & regulation for lagging power factor load :-

From the vector diagram, E can be found out

$$OD = E$$



(Vector diagram for lagging power factor)

For the right angled triangle OBD

$$E = \sqrt{OB^2 + BD^2}$$

$$OB = (OA + AB)$$

$$OB = (V\cos\phi + IR_a)$$

$$BD = (BC + CD)$$

$$BD = (V\sin\phi + IX_s)$$

$$\therefore E = \sqrt{(V \cos \phi + IR_a)^2 + (V \sin \phi + IX_s)^2}$$

- By calculating E , the regulation can be calculated.
Then,


$$\% \text{ Regulation} = \frac{E - V}{V} \times 100$$

Note :- For lagging power factor load, the regulation is positive.

(b) Vector diagram for regulation for leading power factor load :-

- From the vector diagram E can be found out

$$OD = E$$



(Vector diagram for leading power factor)

- From the right angled triangle OB

$$E = \sqrt{OB^2 + BD^2}$$

$$OB = (OC + CB)$$

$$OB = (V \cos \phi + IR_a)$$

$$BD = (Ba - Da)$$

$$BD = (V \sin \phi - I X_s)$$

$$\therefore E = \sqrt{(V \cos \phi + I R_a)^2 + (V \sin \phi - I X_s)^2}$$

→ By calculating E , the regulation can be calculated.


$$\text{Then } \% \text{ regulation} = \frac{E - V}{V} \times 100$$

∴ Note :- For leading power factor load the regulation is negative.

Vector diagram & Regulation for unity power factor load:-

→ From the vector diagram, E can be calculated as

$$OD = E$$



(Vector diagram for unity power factor)

$$\therefore E = \sqrt{OB^2 + BD^2}$$

$$OB = (OA + AB)$$

$$OB = (V + I R_a)$$

$$\therefore E = \sqrt{(V + I R_a)^2 + (I X_s)^2}$$

By calculating E , regulation can be calculated.

Then, % Regulation = $\frac{E-V}{V} \times 100$

General formula :-

→ For lagging & leading power factor load, the following expression is used for determining the value of E .

$$E = \sqrt{(V\cos\phi + IR_a)^2 + (V\sin\phi \pm IX_s)^2}$$

→ When load power factor is unity, then $\cos\phi = 1$

Then, $\quad \quad \quad \& \sin\phi = 0$

$$E = \sqrt{(V + IR_a)^2 + (IX_s)^2}$$

Problem -1 :-

A 3- ϕ star connected alternator is rated at 1600 kVA, 13.5 KV. The armature effective resistance and synchronous reactance are 1.5Ω & 30Ω respectively per phase. Calculate the percentage regulations for a load of 128 kW at p.f of 0.8 leading.

Given Data :-

$$\text{Armature Resistance } (R_a) = 1.5 \Omega$$

$$\text{Synchronous Reactance } (X_s) = 30 \Omega$$

$$\text{Power factor } (\cos\phi) = 0.8$$

To find :-

$$\text{Percentage regulation} = ?$$

Formula used :-

$$\% \text{ regulation} = \frac{E - V}{V} \times 100$$

$$V = 13.5 \text{ kV } \sqrt{3}$$

Solution :-

Let us first find the phase current of the star connected alternator for a load of 1280 kW at P.F of 0.8 leading.

$$1280 \times 103 \times 13500 \times I_L \times 0.8$$

$$\Rightarrow I_L = 68.4 \text{ A}$$

Since the alternator is star connected, it also represents the phase current. Hence, armature phase current $I_a = 68.4 \text{ A}$

$$\therefore I_a R_a = 68.4 \times 1.5$$

$$= 103 \text{ V}$$

$$\therefore I_a X_s = 68.4 \times 30$$

$$= 2050 \text{ V}$$

$$V = 13500 \sqrt{3}$$

$$\Rightarrow V = 7795 \text{ V}$$

$$\therefore E = \sqrt{(7795 \times 0.8 + 103)^2 + (7795 \times 0.6 - 2050)^2}$$

$$= 6910 \text{ V}$$

$$\begin{aligned}\% \text{ regulation} &= \frac{6910 - 7795}{7795} \times 100 \\ &= -11.35 \%. \quad (\text{Ans})\end{aligned}$$

Problem - 2 :-

A 550 V, 55 KVA, single-phase alternator has an effective resistance of 0.2Ω . A field current of 10 A produces an armature current of 200 A on short circuit & an emf of 450 V on open circuit. Calculate

- the synchronous impedance and reactance
- the full-load regulation when the power factor is 0.8 lagging.

Given data :-

$$\text{line voltage } (V_L) = 550 \text{ V}$$

$$\text{Apparent power} = 55 \text{ KVA}$$

$$\text{Armature resistance } (R_a) = 0.2 \Omega$$

$$\text{Field current } (I_f) = 10 \text{ A.}$$

To find :-

- The synchronous impedance & reactance (Z_s)
- The full-load regulation when the power factor is 0.8 lagging.

Formula used :-

$$X_s = \sqrt{Z_s^2 - R_a^2}$$

$$E_0 = \sqrt{(V \cos \phi + I_a R_a)^2 + (V \sin \phi - I_a X_s)^2}$$

$$\% \text{ Regulation} = \frac{E_0 - V}{V} \times 100$$

Solution :-

Synchronous impedance Z_s is,

$$Z_s = \frac{450 \text{ V}}{200 \text{ A}}$$

$$Z_s = 2.25 \Omega$$

$$X_s = \sqrt{Z_s^2 - R_a^2}$$

$$\Rightarrow X_s = \sqrt{(2.25)^2 - (0.2)^2}$$

$$= 2.241 \Omega$$

Synchronous reactance, (X_s) = 2.241 Ω

Full load current is,

$$I_a = \frac{55 \times 10^3}{550}$$

$$= 100 \text{ A.}$$

$$E_0 = \sqrt{(V \cos \phi + I_a R_a)^2 + (V \sin \phi - I_a X_s)^2}$$
$$= \sqrt{(550 \times 0.8 + 100 \times 0.2)^2 + (550 \times 0.6 - 100 \times 2.241)^2}$$
$$= 720.16 \text{ V}$$

Therefore,

$$\% \text{ Regulation} = \frac{E_0 - V}{V} \times 100$$
$$= \frac{720.16 - 550}{550 \times 100} \times 100$$
$$= 30.94 \%$$

\therefore The synchronous impedance and reactance
 $Z_s = 2.25 \Omega$

\therefore The full-load regulation when the power factor is 0.8 lagging = 30.94 %.

Problem - 3 :-

A 50 - kVA , 415 V , 3-Φ, 50 Hz alternator has an effective armature resistance of $0.25 \Omega/\text{phase}$. The synchronous reactance is $3.2 \Omega/\text{phase}$ & leakage reactance is $0.5 \Omega/\text{phase}$, at u.p.f & rated load, determine the

- Internal emf (E_a)
- no-load emf (E_0)
- percentage regulation on full load
- value of synchronous reactance which represents armature reaction.

Given data :-

Apparent power = 50 kVA

line voltage, $V_L = 415 \text{ V}$

Phase = 3 Φ

frequency (f) = 50 Hz

Armature resistance (R_a) = $0.25 \Omega/\text{phase}$

Synchronous reactance (X_s) = $3.2 \Omega/\text{phase}$

Armature reactance (X_a) = $0.5 \Omega/\text{phase}$

Used formula :-

$$E_a = \sqrt{(V + IR_a)^2 + (IX_s)^2} \quad (\text{since it is U.P.F } \sin\theta = 0)$$

$$E_0 = \sqrt{(V + IR_a)^2 + (IX_s)^2}$$

$$\% \text{ regulation} = \frac{E_0 - V}{V} \times 100$$

$$X_a = X_s - X_L$$

Solution :-

$$\therefore V = \frac{415}{\sqrt{3}} = 239.6 \text{ V}$$

$$\therefore I_{FL} = \frac{50 \times 10^3}{\sqrt{3} \times 415}$$

$$= 69.56 \text{ A.}$$

$$\therefore I_{Ra} = I_{FL} \times I_{Ra} = 69.56 \times 0.25$$

$$= 17.39 \text{ V}$$

$$\therefore I_{Xa} = I_{FL} \times X_a = 69.56 \times 0.5$$

$$= 34.78 \text{ V}$$

$$\therefore I_{Xs} = I_F \times X_s$$

$$= 69.56 \times 3.2$$

$$= 222.592 \text{ V}$$

(a) Internal emf $E_a = \sqrt{(V + I_{Ra})^2 + (I_{X_L})^2}$

$$\Rightarrow E_a = \sqrt{(239.6 + 17.39)^2 + (34.78)^2}$$

$$\Rightarrow E_a = 259.33 \text{ V} \quad (\text{Ans})$$

(b) no-load emf (E_0)

$$E_0 = \sqrt{(V + I_{Ra})^2 + (I_{Xs})^2}$$

$$= \sqrt{(239.6 + 17.39)^2 + (222.592)^2}$$

$$= 340 \text{ V} \quad (\text{Ans})$$

(c) % regulation = $\frac{340 - 239.6}{239.6} \times 100$

$$= 41.9 \% \quad (\text{Ans})$$

(d) value of synchronous reactance which represents armature reaction.

$$\begin{aligned}X_a &= X_s - X_L \\&= 3.2 - 0.5 \\&= \underline{\underline{2.7 \Omega}} \quad (\text{Ans})\end{aligned}$$

Problem - 4 :-

A 600 V, 60 KVA, single-phase alternator has an effective resistance of 0.2Ω . A field current of 10 A produces an armature current of 210 A on short circuit and an emf of 480 V on open-ckt.

- Synchronous impedance & reactance.
- Regulation with 0.8 P.F lagging, unity & 0.6 P.F leading.

Given data :-

$$V = 600 \text{ V}$$

$$I_{sc} = 210 \text{ A}$$

$$V_{oc} = 480 \text{ V}$$

$$I_F = 10 \text{ A}$$

$$R_a = 0.2 \Omega$$

Solution :-

The alternator is single phase

$$\text{kVA} = VI \times 10^{-3}$$

$$60 = 600 \times I \times 10^{-3}$$

$$I = 100 \text{ A}$$

$\approx I_a$ (full load current)

$$\text{Now } Z_s = \frac{V_{oc}}{I_{sc}} \quad | \text{ same IP}$$

$$= \frac{480}{210}$$

$$= 2.2857 \approx$$

$$\therefore X_s = \sqrt{Z_s^2 - R_a^2}$$

$$= \sqrt{(2.2857)^2 - (0.2)^2}$$

$$= 2.2769 \approx$$

$$\text{Now } E = \sqrt{(V_{ph} \cos \phi + I_a R_a)^2 + (V_{ph} \sin \phi \pm I_a X_s)^2}$$

+ve sign for lagging
 -ve sign for leading

(i) $\cos \phi = 0.8$ lagging
 $\sin \phi = 0.6$

$$\Rightarrow E = \sqrt{(600 \times 0.8 + 100 \times 0.2)^2 + (600 \times 0.6 + 100 \times 2.2769)^2}$$

$$= 771.608 \text{ V.}$$

$$\therefore \% \text{ regulation} = \frac{E - V}{V} \times 100$$

$$= \frac{771.608 - 600}{600} \times 100$$

$$= 28.6 \% \quad (\text{Ans})$$

(ii) $\cos \phi = 1, \sin \phi = 0$

$$E = \sqrt{(600 \times 1 + 100 \times 0.2)^2 + (600 \times 0 + 100 \times 2.2769)^2}$$

$$\Rightarrow E = 660.486 \text{ V.}$$

$$\therefore \% \text{ regulation} = \frac{660.484 - 600}{600} \times 100 \\ = 10.08 \% \quad (\text{Ans})$$

(iii) $\cos \phi = 0.6$ (leading)
 $\sin \phi = 0.8$

$$E = \sqrt{(600 \times 0.6 + 100 \times 0.2)^2 + (600 \times 0.8 - 100 \times 2.2769)^2} \\ = 456.136 \text{ V}$$

$$\% \text{ regulation} = \frac{456.136 - 600}{600} \times 100 \\ = -23.97 \quad (\text{Ans})$$

Problem - 5 :-

A 3Ø, star connected alternator is rated at 1600 KVA, 13500 Volts. The armature resistance & synchronous reactance are 1.5Ω & 30Ω respectively per phase. Calculate the percentage regulation for a load of 1280 KW at a P.F 0.8 lag, U.P.F 0.8 lead.

Given data :-

$$\text{KVA} = 1600 \text{ KVA}$$

$$V_L = 13500 \text{ V}$$

$$R_a = 1.5 \Omega$$

$$X_s = 30 \Omega$$

$$V_{ph} = \frac{V_L}{\sqrt{3}} = \frac{13500}{\sqrt{3}} = 7794.2286 \text{ V} \\ (\text{star connected})$$

Solution :-

case - 1 :-

$$\cos \phi = 0.8 \text{ lag},$$

$$\sin \phi = 0.6$$

$$P_{out} = \sqrt{3} V_L I_L \cos \phi$$

$$\therefore 1280 \times 10^3 = \sqrt{3} \times 13500 \times I_L \times 0.8$$

$$\Rightarrow I_L = 68.4266 \text{ A} = I_{aph}$$

$$\begin{aligned} \therefore E_{ph}^2 &= (V_{ph} \cos \phi + I_a R_a)^2 + (V_{ph} \sin \phi + I_a X_a)^2 \\ &= (7794.2286 \times 0.8 + 68.426 \times 1.5)^2 + \\ &\quad (7794.2286 \times 0.6 + 68.426 \times 30)^2 \end{aligned}$$

$$\Rightarrow E_{ph} = 9244.1772 \text{ V.}$$

$$\begin{aligned} \% \text{ Regulation} &= \frac{E_{ph} - V_{ph}}{V_{ph}} \times 100 \\ &= \frac{9244.1772 - 7794.2286}{7794.2286} \times 100 \\ &= 18.6\%. \end{aligned}$$

Case - 2 :-

$$\cos \phi = 1, \sin \phi = 0$$

$$P_{out} = \sqrt{3} V_L I_L \cos \phi$$

$$\therefore 1280 \times 10^3 = \sqrt{3} \times 13500 \times I_L \times 1$$

$$\Rightarrow I_L = 54.7413 \text{ A} = I_{aph}$$

$$\therefore E^2_{Ph} = (7794.2286 \times 1 + 54.7413 \times 1.5)^2 \\ + (0 + 54.7413 \times 30)^2$$

$$E_{Ph} = 8045.7249 \text{ V}$$

$$\% \text{ Regulation} = \frac{E_{Ph} - V_{Ph}}{V_{Ph}} \times 100 \\ = \frac{8045.7249 - 7794.2286}{7794.2286} \times 100 \\ = 3.22 \%$$

Case - 3 :-

$$\cos \phi = 0.8 \text{ lead}$$

$$\sin \phi = 0.6$$

$$P_{out} = \sqrt{3} V_L I_L \cos \phi$$

As $\cos \phi = 0.8$, the current I_L is same as in case 1

$$I_L = 68.426 \text{ A} = I_{aph}$$

$$\therefore E^2_{Ph} = (7794.2286 \times 0.8 + 68.426 \times 1.5)^2 \\ + (7794.2286 \times 0.6 - 68.426 \times 30)^2 \\ = 6859.6372 \text{ V}$$

$$\% \text{ Regulation} = \frac{6859.6372 - 7794.2286}{7794.2286} \times 100 \\ = -11.89 \%$$

Necessity of parallel operation of alternator


Parallel operation of alternators :-

- The operation of connecting an alternator in parallel with another alternator or with common bus-bars is known as synchronizing.
- The alternators are used in a power system where they are in parallel with many others alternators.
- The alternator is connected to a live system of constant voltage & constant frequency.
- The electrical system to which the alternator is connected, has already so many alternators & loads connected to it that no matter what power is delivered by the incoming alternator.
- The voltage & frequency of the system remains the same.
- The alternator is said to be connected to infinite bus-bars.
- The connecting of stationary alternators to live bus-bars, because, stator induced emf being zero, a short-circuit will result.
- The proper synchronization of alternators, the following three conditions must be satisfied.

- The terminal voltage of the incoming alternators must be the same as bus-bars voltage.
 - The speed of the incoming machine must be such that its frequency ($f = PN/120$) equals bus-bars frequency.
 - The phase of the alternator voltage must be identical with the phase of the bus-bars voltage.
 - It means that the switch must be closed at the instant the two voltages have correct phase relationship.
- Condition 1 is indicated by a voltmeter, Condition 2 & 3 are indicated by synchronizing lamps on a synchronoscope.


Synchronizing of alternators :-

Single phase alternators :-




(Synchronizing of alternators)

- The machine 2 is to be synchronized with "put on" the bus-bars to which machine 1 is already connected.
- This is done with the help of two lamps L_1 & L_2 connected as shown in figure.
- The E_1 & E_2 are in-phase relative to the external circuit but are in direct phase opposition in the local circuit.
- The speed of the incoming machine 2 is not brought up to that of machine 1, then its frequency will also be different, hence there will be a phase-difference between their voltages.
- The phase-difference will be continuously changing with the changes in their frequencies.
- The result is that their resultant voltage will undergo changes similar to the frequency changes of beats produced.
- When two sound source of nearly equal frequency are sounded together, as shown in figure,
- The resultant voltage is maximum & some other times minimum.
- The current is alternatingly maximum & minimum.
- Due to this changing current through the lamps, a flicker will be produced.



(Waveform)

- The frequency of flicker being ($f_2 - f_1$), lamps will dark out & glow up alternately.
- Dark ness indicates that the two voltages E_1 & E_2 are in exact phase opposition relative to the local circuit & hence there is no resultant current through the lamps.
- Synchronizing is done at the middle of the dark period. That is why, sometimes, it is known as 'lamps dark' synchronizing.



→ The lamps will glow brightest when the two voltages are in phase with the bus-bar voltage because then voltage across them is twice the voltage of each machine.

Necessity for parallel operation of alternators

- Alternators ^{are} operated in parallel for the following reasons.
 - (i) Several alternators can supply a bigger load than a single alternator.
 - (ii) One or more alternators may shut down during the period of light loads. Thus, the remaining alternator operates at near or full load with greater efficiency.
 - (iii) When one machine is taken out of service for its scheduled maintenance and inspection the remaining machines maintain the continuity of the supply.
 - (iv) If there is a break down of the generator, there is no interruption of the power supply.
 - (v) Number of machines can be added with disturbing the initial installation according to the requirement to fulfill the increasing future demand of the load.
 - (vi) Parallel operation of the alternators, reduces the operating cost of energy generation.


Requirement for parallel operation :-

The following conditions should be satisfied for parallel operation are as follows ;


- The phase sequence of the Bus bar voltages & the incoming machine voltage must be the same.
- The bus bar voltages and the incoming machine terminal voltage must be in phase.
- The terminal voltage of the incoming machine and the alternator which is to be connected in parallel or with the bus - bar voltage should be equal.
- The frequency of the generated voltage of the incoming machine & the frequency of the voltage of the bus bar should be equal.

Three - phase Alternators :-

- Three-phase alternators, it is necessary to synchronize one phase only , the other two phases will then be synchronized automatically.
- first it is necessary that the incoming alternators is correctly 'phased out' i.e , the phases are connected in the proper order of R, Y, B & not R, Y, B etc.
- Three lamps are used. But they are deliberately connected asymmetrically , as shown in figures.





Asymmetrical Connection



Schematic diagram

- This transposition of two lamps, suggested by Siemens and Halske, helps to indicate whether the incoming machine is running too slow.



- The lamps were connected symmetrically, they would dark out or glow up simultaneously (If the phase rotation is the same as that of the bus-bars).
- Lamp L_1 is connected between R & R' , L_2 between Y & Y' (not Y & Y') & L_3 between B & Y' (and not B & B') as shown in figure.
- Voltage stars of two machines are shown superimposed on each other in figure.




(Voltage stars of two machines)

- Two sets of start vectors will rotate at unequal speeds if the frequencies of the two machines are different.
- The incoming alternator is running faster, then voltage start $R'Y'B'$ will appear to rotate anti-clockwise with respect to the bus-bar.
- The voltage start RYB at a speed corresponding to the difference between their frequencies.
- The voltage across L_1 is RR' & is seen to be increasing from zero.
- The voltage across L_1 is RR' and is seen to be increasing from zero.
- The voltage across L_2 is YB' which is decreasing, having just passed through its maximum.
- The voltage across L_3 is BY' which is increasing & approaching its maximum.
- The lamps will light up one after the others in the orders $2, 3, 1$; $2, 3, 1$ or $1, 2, 3$.
- The incoming machine is slightly slower.
- The start $R'Y'B'$ will appear to be rotating clockwise relative to voltage start RYB .
- The voltage across L_3 i.e., $Y'B'$ is decreasing having just passed through its maximum.
- The voltage across L_2 i.e. YB' is increasing & approaching its maximum.
- The voltage across L_1 is decreasing having passed through its maximum.

→ The lamps will light up one after the other in the orders 3, 2, 1 ; 3, 2, 1 etc. which is just the reverse of the first order.



Voltage stars of two machines



Mounting of three lamps

- The three lamps are mounted at the 3 corners of a triangle & the apparent direction of rotation of light indicates whether the incoming alternator is running too fast or too slow.
- Synchronization is done at the moment the uncrossed lamp L_1 is in middle of the dark period.
- When the alternator voltage is too high for the lamps to be used directly.
- The step-down T/F's are used & the synchronizing lamps are connected to the secondaries.
- When the uncrossed lamp L_1 is dark, the other two 'crossed' lamps L_2 & L_3 are dimly but equally bright.
- Hence, this method of synchronizing is also sometimes known as "two bright & one dark" method.
- The synchronization by lamps is not quite accurate, because to a large extent, it depends on the sense of correct judgment of the operator.
- To eliminate the element of personal judgment in routine operation of alternators.
- The machines are synchronized by a more accurate device called a synchroscope.
- The 3 stationary coil & a rotating iron vane which is attached to a pointer.

- Out of three coils, a pair is connected to one phase of the line & the other to the corresponding machine terminals, potential transformer being usually used.
- The pointer moves to one side or the other from its vertical position depending on whether the incoming machine is too fast or too slow.
- For correct speed, the pointer points vertically up.

Condition for parallel operation of Alternators

Parallel operation of Alternators :-

- The process of connecting two or more alternators in parallel to share a common load is called operation of Alternators.

Conditions for parallel operation of Alternators :-

- Let us see the condition for parallel operation of alternators one by one.


Condition - 1 :-

Equal terminal voltages :-

- This is obtained by adjustment of the incoming generator's field strength.

Bus bars

R
Y
B



Synchronizing switch

Machine
in operation

Incoming
machine

(synchronization of alternators)

Condition - 2 :-

→ Equal frequencies :-

This is obtained by adjusting the incoming generator's prime-mover speed.

Bus bars

R
Y
B

A
Machine
operation

B
Incoming
machine

Synchronizing
switch


(synchronization of Alternators)

Condition - 3 :-

same phase sequence :-

- This is obtained by adjusting the conditions of the alternators which connect in parallel.

Bus bars



(synchronization of Alternators)

Synchronization :-

- This is the term which is frequently used in parallel operation of alternators.
- The method of connecting the alternators in parallel is known as synchronization.

Synchroscope


④ synchroscope 4 methods are here :-

- (i) Dark lamp method
- (ii) Bright lamp method
- (iii) Dark & bright lamp method
- (iv) synchroscope method.

① Dark lamp method :-

- In dark lamp method of synchronising , three lamp are connected as shown in figure,
- The alternator 1 is already connected with the busbar & is supplying power to the load.
- The alternator 2 is the incoming alternator.
- Incoming alternator (2) is started & its speed is adjusted to its rated value.
- The voltage & frequency of the system remain the same.
- The excitation of incoming alternator is adjusted to generate its rated voltage.
- Voltmeter V_1 will indicate the generated voltage of existing alternator voltage.
- Voltmeter V_2 will indicate the generated voltage of incoming alternator.
- To verify the condition I, for synchronisation, voltage indicated by the voltmeter V_1 & V_2 are observed.

- When the voltages V_1 & V_2 are equal, condition 1 is satisfied.
- The phase sequence of the incoming alternator & existing alternator can be checked by using phase sequence indicator.
- The 3 lamps in the circuit are glowing uniformly together & becomes dark together, then it indicates that the phase sequence is correct.



- The sequence of the incoming alternator is same as that of existing alternator, the synchronising lamps will start flickering in uniform.
- The output terminals of the incoming alternator changed properly.


- There is any difference in frequency, of the alternators, the lamp will be bright & dark alternatively.
- The speed of alternators 2 is adjusted properly so that flickering of lamps is slower in rate.
- The lamps flicker at a very slow rate, it indicates that the frequencies of the two alternators are almost equal.
- At this condition the synchronising switch is closed at the middle of all the 3 dark lamps.
- When the synchronizing switch is closed, the alternator 2 is just connected to the bus bar.
- At this stage generated emf of the incoming alternator is just equal to the bus bar voltage.
- It neither supplies power nor receives the power from the bus bar and the alternator 2 is said to be "floating on the busbar".

Demerits :-

- It is not possible to judge whether the incoming alternator is fast or slow.
- The lamps can be dark even through a small value of voltage may present across its terminals. The bright lamp method eliminates these disadvantages.


Bright lamp method :-

- In bright lamp method of synchronising all the 3 lamps are cross connected as shown in figure.
- The lamps will glow the brightest when the two voltages are in phase, because the voltage across the lamp is twice the voltage of each alternators.
- Now the incoming alternator is started and its speed is adjusted to its rated speed.
- Field excitation is also adjusted to generate the rated voltage.
- When the voltage V_1 & V_2 are equal the condition 1 is satisfied.
- The phase sequence is checked by the use of phase sequence indicator or using 3 lamps.
- If the sequence of the incoming alternator is same as that of existing alternator, the synchronising lamps will start flickering in uniform.
- If not so, the output terminals of the incoming alternator will be changed properly.
- The frequency of the incoming machine is adjusted to the existing alternator frequency by adjusting the speed of the incoming alternator.
- The synchronising switch is closed at the middle of the brightest period of the lamps & thus the alternator is synchronised.



③ Dark & Bright lamp method :-

→ In this method, 3 lamps are connected as shown in figure.



- first the incoming alternator is allowed to run at its rated speed.
- Its generated e.m.f is adjusted to a value equal to the existing alternator's voltage by varying the field excitation of incoming alternator.
- the phase sequence is checked with the help of a phase sequence indicator.
- when the voltage V_1 & V_2 are equal the condition 1 is satisfied.
- In this method , the voltage across the lamps is different and thus the lamps will not flicker in uniform.
- Depending upon the frequency of incoming alternator , the order of brilliance of the lamps may be varied.
- If f_1 is the frequency of existing alternator and f_2 is the frequency of the incoming alternator.

Condition for incoming machine :-

- for the condition the incoming machine is slower, i.e, f_1 is greater than f_2 ($f_1 > f_2$), now lamp L_1 is dying out , lamp L_2 has already passed its point of maximum brilliance & lamp L_3 is approaching maximum brilliance.
- The order of brilliance of the lamps is L_2, L_3 & L_1 i.e, L_1, L_2, L_3 .


- for the condition the incoming machine, is faster i.e., ($f_2 > f_1$) the order of brilliance of the lamps is $L_1, L_3 \& L_2$.
- Synchronising switch is closed during dark period of the lamp L_1 .
-

④ Synchroscope :-

- The Synchroscope is an instrument for indicating difference of phase & frequency between two voltages & at the same time it also indicates whether alternator is running slow or fast.
- It is a motor having a pointer fixed at one end of the motor's shaft which rotates over a circular scale fixed at the end of the shaft.

Principle of synchroscope :-


- The Synchroscope works on the principle of rotating magnetic field.
- constructional details of synchroscope :-
- It consists of a rotor & stator wound for two phase system.
- The rotor & stator is supplied from two phase supply from the alternators to be connected in parallel.
- If the two phases are synchronized, then the third phase will automatically be synchronized.



- The supply to stator of synchroscope is given by existing alternators.
- The supply to rotor of synchroscope is given by incoming alternators.

Functions of Synchroscope :-

- It indicates difference in phase & frequencies of alternators which are to be connected in parallel.
- It also indicates whether the coming alternators is running slow or fast.




Synchroscope

Working of synchroscope :-

- The working of the synchroscope depends upon the difference in frequency of alternators which are to be connected in parallel.
- If there is no difference in frequency of rotor & stator supply then the rotor remains stand still.
- If there difference in frequencies of rotor & stator supply, the rotor will rotated,
- If the difference in frequencies is greater, The rotor speed to be greater,
- If the difference in frequencies is less, the rotor speed will be less.

Synchroscope method :-

- Synchroscope of an alternators by using lamps is not very exact method. since it requires a correct judgement for closing the synchronizing switch.
- If there is a small angle of phase displacement, It causes disturbance to the alternators,
- In this method, synchroscope is used instead of lamps.
- The synchroscope indicates the instant of synchronism more correctly.
- The synchroscope is connected as shown in figure.
- The synchroscope consists of a rotor and a stator.
- The rotor on the moving coils is connected to the incoming alternator & the stator or the fixed coil is connected to the existing alternator, or the bus bars.



Synchroscope
method


- In the synchroscope, a pointer is attached to the rotors.
- This pointer will indicate the connect time for closing the synchronising switch.
- The connect time for synchronising is when the pointer in the synchroscope is stationary at 12' o'clock position.
- If frequencies are different values, the pointer will rotate.
- If the pointer indicates in the anti-clockwise direction, the frequency of the incoming alternator is low.
- The clockwise direction of rotation of the pointer shows the frequency of the incoming alternator is higher than the frequency of the alternator 1.
- In this method also the voltages are checked first by providing voltmeters.
- The field rheostat of incoming alternators is adjusted such that the two alternators voltage must be equal.

- Then the phase sequence is checked by using phase sequence indicator on the test circuit.
- If the voltage values & the phase sequence is correct, the speed of the incoming alternator is adjusted in such a way the pointer of the synchroscope rotates very slowly.
- If the frequencies are equal, the pointer is at stationary position.
- The synchronising switch of the incoming alternator is closed, when the pointer is stationary at 12' O'clock position in the synchroscope.
- This is the correct instant for closing the synchronising switch.

(Synchronising Current,
Synchronising Power)

Parallel operation of two alternators :-

Let us assume that the two alternators with identical speed - load characteristics running in parallel with a common terminal voltage (V) Volts & load impedance (Z) as shown in figure.



(Parallel operation of two alternators)

→ Assume the generated emf of two machines 1 & 2 are E_1 & E_2 respectively & the synchronous impedance per phase Z_1 & Z_2 respectively.

$$V = E_1 - I_1 Z_1$$

$$V = E_2 - I_2 Z_2$$

where,

E_1 : induced emf alternator 1

E_2 : induced emf alternator 2

I_1 : Alternator current I_1

I_2 : Alternator current I_2

$$\therefore E_1 - E_2 = I_1 Z_1 - I_2 Z_2$$

Also, $I = I_1 + I_2$ & $V = IZ$

$$\therefore E_1 = I_1 Z_1 + IZ$$

$$\Rightarrow E_1 = I_1 (z + z_1) + I_2 z$$

$$\therefore E_2 = I_2 Z_2 + IZ$$

$$\Rightarrow E_2 = I_2 (z + z_2) + I_1 z$$

$$\therefore I_1 = \frac{(E_1 - E_2)z + E_1 Z_2}{z(z_1 + z_2) + Z_1 Z_2}$$

$$\therefore I_2 = \frac{(E_2 - E_1)z + E_2 Z_1}{z(z_1 + z_2) + Z_1 Z_2}$$

$$I = \frac{E_1 Z_2 + E_2 Z_1}{z(z_1 + z_2) + Z_1 Z_2}$$

$$\therefore V = IZ$$

$$\Rightarrow V = \frac{E_1 Z_2 + E_2 Z_1}{z_1 + z_2 + (Z_1 Z_2 / z)}$$

$$I_1 = \frac{E_1 - V}{Z_1}$$

The circulating current under no-load condition

$$I_c = \frac{(E_1 - E_2)}{(Z_1 + Z_2)}$$

Problem - 1 :-

Two single phase alternators operating in parallel have induced emf's in open circuit of $230 \angle 0^\circ$ & $230 \angle 10^\circ$ volt & respective reactance of $j2 \angle 0^\circ$ & $j3 \angle 0^\circ$

Calculate (i) Current

(ii) Terminal Voltage

(iii) power delivered by each of the alternators to a load of impedance $6 \angle 0^\circ$ (respective)

Soln

Given data :-

$$Z_1 = j2 \angle 0^\circ$$

$$Z_2 = j3 \angle 0^\circ$$

$$Z = j6 \angle 0^\circ$$

$$E_1 = 230 \angle 0^\circ \text{ V}$$

$$E_2 = 230 \angle 10^\circ \text{ V}$$

To find :-

$$I_1, I_2 = ?$$

$$V = ?$$

$$P_1, P_2 = ?$$

Solution :-

$$E_1 = 230 \angle 0^\circ \text{ V}$$

$$E_2 = 230 \angle 10^\circ \text{ V}$$

$$E_2 = 230 (0.985 + j 0.175)$$

$$\Rightarrow E_2 = (226.5 + j 39.9) \text{ V}$$

$$\begin{aligned}
 \text{(i) } I_1 &= \frac{((\epsilon_1 - \epsilon_2)z + \epsilon_1 z_2)}{(z(z_1 + z_2) + z_1 z_2)} \\
 &= \frac{(230 + j10) - (226.5 + j39.9) \times 6 + (230 \times j3)}{6(z_2 + j3) + j2 \times j3} \\
 &= (14.3 - j3.56) \\
 &\approx 14.73 \angle -14^\circ \text{ A}
 \end{aligned}$$

$$\begin{aligned}
 \therefore I_2 &= \frac{((\epsilon_2 - \epsilon_1)z + \epsilon_2 z_1)}{(z(z_1 + z_2) + z_1 z_2)} \\
 &= (22.8 - j1.2) \\
 &\approx 22.83 \angle -3.4^\circ
 \end{aligned}$$

$$\begin{aligned}
 \therefore I &= I_1 + I_2 \\
 &\approx 37.1 - j4.7 \\
 &\approx 37.4 \angle -7.3^\circ
 \end{aligned}$$

$$\begin{aligned}
 \therefore V &= IZ \\
 &= (37.1 - j4.7) \times 6 \\
 &\approx 222.6 - j28.2 \\
 &\approx 224 \angle -7.3^\circ
 \end{aligned}$$

$$\begin{aligned}
 \therefore P_1 &= VI_1 \cos \phi_1 \\
 &= 224 \times 14.73 \times \cos 14^\circ
 \end{aligned}$$

$$\therefore P_1 \approx 3201 \text{ W}$$

$$\begin{aligned}
 \therefore P_2 &= VI_2 \cos \phi_2 \\
 &\approx 224 \times 22.83 \times \cos 3.4^\circ \\
 &\approx 5105 \text{ W}
 \end{aligned}$$

Load sharing

load sharing between two alternators :-

- When an alternator is synchronized, the load can be shifted from the existing alternator to the incoming alternator which is to be connected in parallel.
- Load sharing between the alternators can be changed by altering the mechanical input to the prime movers.

Condition for load sharing between two alternators depends on :-

- Synchronous generators running in parallel must run at same frequency.
- Speed power characteristics of the prime movers driving the two alternators in parallel decides the load division between the two.
- The electrical power of the alternators in parallel is determined by mechanical input.
- The electrical power output of alternators in parallel is determined by mechanical input.
- Changes in excitation of the alternators results in change of voltage but the division of active power remains almost unaffected.

control of active load (kW) & reactive load (kVAR)

- The reactive load (kVAR) supplied by each alternator operating in parallel is controlled by controlling the excitation of it.
- When the excitation of one of the alternators is increased, the reactive power (kVAR) supplied by that alternator will be increased.
- When the excitation of one of the alternators is decreased, the reactive power (kVAR) supplied by that alternator will be decreased.
- The change of excitation does not make any change in the active power (kW) supplied by the alternator.
- The active load (kW) supplied by each alternator operating in parallel is controlled by controlling the input power applied to it.
- When the input power of one of the alternators is increased, the active power (kW) supplied by that alternator will be increased.
- When the input power of one of the alternators is decreased, the active power (kW) supplied by that alternator will be decreased.


Infinite bus bar :-

- Alternator generally feed power into power system.
- Power system consists of a large number of alternators interconnected.

- The size of the system is very large. Hence removing of an alternator or adding an alternator with the system does not affect the system voltage & frequency.
- The very large system working at constant voltage & frequency is called an infinite bus bar system.
- The behaviour of the infinite bus bar system is same as a large generator having zero internal impedance ($Z_s/oo = 0$).
- The speed of an alternator connected to an infinite bus bar is fixed corresponding to the system frequency.
- If an alternator is to be shut down from the infinite bus bars, the KW loads must be removed first by reducing the input power to the alternator.
- The reactive load must be removed reducing the excitation.
- When there is no real load & load reactive load on the alternators, it floats on the bus bars neither taking current nor delivering current.
- The alternator can be disconnected from the bus bars when it floats.

A more alternative expression for synchronizing power

→ let V & E be the terminal voltage & induced emf per phase of the rotor. Then, taking $V = V \angle 0^\circ$, the load current supplied by the alternator.



$$I = \frac{E - V}{Z_s}$$

$$\Rightarrow I = \frac{E \angle \alpha - V \angle 0^\circ}{Z_s \angle 0^\circ}$$

$$\Rightarrow I = \frac{E}{Z_s} \angle \alpha - \frac{V}{Z_s} \angle 0^\circ$$

$$\Rightarrow I = \frac{E}{Z_s} [\cos(\theta - \alpha) - j \sin(\theta - \alpha)]$$

$$\Rightarrow I = -\frac{V}{Z_s} (\cos \theta - j \sin \theta)$$

$$\Rightarrow I = \left[\frac{E}{Z_s} \cos(\theta - \alpha) - \frac{V}{Z_s} \cos \theta \right] - j \left[\frac{E}{Z_s} \sin(\theta - \alpha) - \frac{V}{Z_s} \sin \theta \right]$$

→ These components represent the $I \cos \alpha$ & $I \sin \alpha$ respectively. The power P converted internally is given by the sum of the product of corresponding components of the current with $E \cos \alpha$ & $E \sin \alpha$.

$$\therefore P = E \cos \alpha \left[\frac{E}{Z_s} \cos(\theta - \alpha) - \frac{V}{Z_s} \cos \theta \right] + E \sin \alpha \left[\frac{E}{Z_s} \sin(\theta - \alpha) - \frac{V}{Z_s} \sin \theta \right]$$

$$\Rightarrow P = E \left[\frac{E}{Z_s} \cos \theta \right] - E \left[\frac{V}{Z_s} \cos(\theta + \alpha) \right]$$

$$\Rightarrow P = \frac{E}{Z_s} [E \cos \theta - V(\cos \theta + \alpha)] \text{ per phase}$$

→ Now, let, for some reason, angle α be changed to $(\alpha \pm \delta)$. Since V is held rigidly constant due to displacement $\pm \delta$, an additional emf of divergence i.e., $P_{sy} = E_{sy}/Z_s$. The internal power will become.

$$P^1 = \frac{E}{Z_s} [E \cos \theta - V \cos(\theta + \alpha \pm \delta)]$$

The difference between P^1 & P gives the synchronizing power.

$$\therefore P_{sy} = P^1 - P = \frac{EV}{Z_s} [\cos(\theta + \alpha) - \cos(\theta + \alpha \pm \delta)]$$

$$\Rightarrow P_{sy} = \frac{EV}{Z_s} [\sin \delta \sin(\theta + \alpha) \pm 2 \cos(\theta + \alpha) \sin^2 \delta]$$

→ If δ is very small, then $\sin^2(\delta/2)$ is zero, hence
PSY per phase

$$\text{PSY} = \frac{EV}{Z_s} \sin(\theta + \alpha) \sin \delta$$

→ In large alternators, R_a is negligible, hence
 $\tan \theta = X_s/R_a = \infty$, so that $\theta = 90^\circ$.
Therefore, $\sin(\theta + \alpha) = \cos \alpha$

$$\begin{aligned}\therefore \text{PSY} &= \frac{EV}{Z_s} (\cos \alpha \sin \delta \text{ per phase}) \\ &= \frac{EV}{X_s} \cos \alpha \sin \delta \text{ per phase}\end{aligned}$$

→ Consider the case of synchronizing an unloaded machine on to a constant voltage bus-bars. For proper operation, $\alpha = 0$ so that E coincides with V . In that case $\sin(\theta + \alpha) = \sin \theta$.

$$\therefore \text{PSY} = \frac{EV}{Z_s} \sin \theta \sin \delta \text{ from above}$$

since δ is very small, $\sin \delta = \delta$

$$\therefore \text{PSY} = \frac{EV}{Z_s} \delta \sin \theta$$

$$\therefore \text{PSY} = \frac{EV}{X_s} \delta \sin \theta$$

Usually, $\sin \theta \approx 1$, hence

$$\therefore \text{PSY} = \frac{EV}{Z_s} \delta$$


$$\Rightarrow \text{PSY} = V \left(\frac{E}{Z_s} \right) \delta$$

$$\Rightarrow \text{Psy} = V \left(\frac{E}{X_s} \right) \delta$$

$$\Rightarrow \text{Psy} = VI_{sc} \delta \text{ per phase}$$

EFFECT OF UNEQUAL VOLTAGES :-

- Consider two alternators, which are running exactly in-phase but which have slightly unequal voltages, as shown in figure.



(Effect of unequal voltages)

- If E_1 is greater than E_2 , then their resultant is $E_r = (E_1 - E_2)$ & is in-phase with E_1 . Their E_r or E_{sy} set up a local synchronizing current I_{sy} which is almost 90° behind E_{sy} & hence behind E_1 also.
- The lagging current produces demagnetising effect on the first machine, hence E_1 is reduced.
- The other machine runs as a synchronous motor taking almost 90° leading current. hence its field is strengthened due to magnetising effect of armature reaction. This tends to increase E_2 .

→ The two effects act together & hence lessen the inequalities between the two voltages & tend to establish stable conditions.

Distribution of load :-

- The amount of load taken up by an alternator running, in parallel with other machines, is solely determined by its driving torque. i.e., by the power input to its prime mover.
- Any alteration in its excitation merely changes its KVA output, but not its KW output.
- In other words, it merely changes the power factors at which the load is delivered.


Effect of change in excitation :-

- The initial operating conditions of the two parallel alternators are identical i.e., each alternator supplies one half of the active load (KW) & one half of the reactive load (KVAR), the operating power factors thus being equal to the load p.f.
- The active & reactive powers are divided equally thereby giving equal apparent power triangles for the two machines as shown in figure.
- Each alternator supplies a load current I so that Output current is $2I$.

- the excitation of alternator No.1 be increased, so that E_1 becomes greater than E_2 .
- The difference between the two e.m.f's set up a circulating current $I_c = I_{sy} = \underline{(E_1 - E_2)}$ which is confined to the local path through the armatures and round the bus-bars. This current is superimposed on the original current distribution.
- I_c is vectorially added to the load current of alternator No.1 and subtracted from that of No.2.
- The two machines now deliver load currents I_1 & I_2 at respective power factors of $\cos \phi_1$ & $\cos \phi_2$.
- The change in load currents lead to changes in power factors, such that $\cos \phi_1$ is reduced, whence as $\cos \phi_2$ is increased. Effect on the KW loading of the two alternators is negligible, but KVAR₁ supplied by alternator No.1 is increased whereas KVAR₂ supply by alternator No.2 is correspondingly decreased, as shown by the KVA triangles of figure.
- Effect on the KW loading of the alternators is negligible, but KVAR₁ supplied by alternator No.1 is increased, whereas KVAR₂ supplied by alternator No.2 is correspondingly decreased, as shown by the KVA triangles of figure.

Effect of change in steam supply :-


- Now, suppose that excitations of the two alternators are kept the same but steam supply to alternator No. 1 is increased i.e., power input to its prime mover is increased.
- The speed of the two machines are tied together by their synchronous bond, machine No. 1 can not overrun machine No. 2.
- Alternatively, it utilizes its increased power input for carrying more load than No. 2.
- It can be made possible only when rotor no. 1 advances its angular position with respect to No. 2 as shown in figure, where E_1 is shown advanced ahead of E_2 by an angle α .
- Consequently, resultant voltage E_{rc} is produced which, acting on the local circuit sets up a current I_{sy} which lags by almost 90° behind E_{rc} but is almost in phase with E_1 .



Equal excitations

Equal steam supply

Equal speeds



Equal excitation


steam supply - 1 >

steam supply - 2

equal speeds

steam supply)

(Effect of change in steam supply)



(Effect of change in steam supply)

- Hence power per phase of No.1 is increased by an amount = $E_1 I_{sy}$ whereas that of No.2 is decreased by the same amount.
- I_{sy} has no appreciable reactive component, the increase in steam supply does not disturb the division of reactive power, but it increases the active power output of alternator No.1. and decreases that of No.2. Load division, when steam supply to alternator No.1. increased, is shown in figure.
- It is found that by increasing the input to its prime mover, an alternator can be made to take a greater share of the load, through at a different power factor.
- The points worth remembering are
 - (i) The load taken up by an alternator directly depends upon its driving torque or in other words, upon the angular advance of its rotor.

- ⑥ The excitation merely changes the p.f at which the load is delivered with out affecting the load so long as steam supply remains unchanged.
- ⑦ If input to the prime movers of an alternators is kept constant, but its excitation is changed, then KVA components of its output is changed , NOT KW.

Problems on load sharing

Problem 1 :-

To identical , 3 phase star connected alternators operating in parallel , share equally to total load of 750 KW of 600 v. and pf 0.8 . The synchronous reactance & resistance of each machine are respectively $50\ \Omega$ & $2.5\ \Omega$ per phase . The field of the first alternator is excited so that the armature current is 40 A. lagging.

Find :-

- (i) The armature current of the second alternator
- (ii) The power factor of each machine.

Given Data :-

$$\text{Total load} = 750 \text{ KW}$$

$$\text{load voltage} = 600 \text{ V}$$

$$\text{load p.f} = 0.8 \text{ lagging}$$

$$X_s/\text{ph} = 50\ \Omega$$

$$R_a/\text{ph} = 2.5\ \Omega$$

$$I_1 = 40 \text{ A}$$

To find :-

$$I_2 = ?$$

$$\cos \phi_2 = ?$$

$$\text{load current } (I_L) = \frac{750 \times 10^3}{(\sqrt{3} \times 6000 \times 0.8)}$$

$$= 90.21 \text{ A}$$

$$\text{Active component of } I_L = 90.21 \times 0.8$$

$$I_L = 72.168 \text{ A}$$

$$\text{Reactive component of } I_L = 90.21 \times 0.6$$

$$= 54.126 \text{ A}$$

The power supply is unchanged

Active component of both the machine remains the same.

$$= \frac{72.168}{2}$$

$$= 36.084 \text{ A}$$

Due to variation in excitation of 1st machine the reactive component of load would vary due to change in excitation.

Therefore, Reactive component of 1st machine after changing excitation

$$= 40^2 - (36.084)^2$$

$$= 17.261 \text{ A}$$

Reactive component of 2nd machine

$$= 54.126 - 17.261$$

$$= 36.865 \text{ A}$$

$$\therefore I_2 = \sqrt{(36.084)^2 + (36.865)^2}$$

$$= 51.585 \text{ A.}$$

$$\therefore \cos \phi_1 = \frac{36.084}{40}$$

$$= 0.9021 \text{ lag.}$$

$$\therefore \cos \phi_2 = \frac{36.084}{51.585}$$

$$= 0.699 \text{ lag.}$$

Problem - 2 :-

Two 20 MVA, 3Ø alternators operate in parallel to supply a load of 35 MVA at 0.8 p.f lagging. If the output of one machine is 25 MVA at 0.9 lagging, what is the output and p.f of the other machine?

Given Data :-

$$P_1 = 25 \text{ MVA}$$

Power factor 1 = 0.9 lagging.

Rating of alternators = 20 MVA.

No of alternators = 2

Total load = 35 MVA

Load p.f = 0.8 lagging.

To find :-

$$P_2 = ?$$

Power factor 2 = ?

Solution :-

$$\text{load MW} = 35 \times 0.8 \\ = 28$$

$$\text{load MVAR} = 35 \times 0.6 \\ = 21$$

from first machine data,

$$\cos \phi_1 = 0.9 \text{ lagging}$$

$$\sin \phi_1 = 0.436 \text{ lagging}$$

$$\text{MVA}_1 = 25$$

we obtain,

$$\text{MW}_1 = 25 \times 0.9 \\ = 22.5$$

$$\text{MVAR}_1 = 25 \times 0.436 \\ = 10.9$$

from second machine data,

we find,

$$\text{MW}_2 = \text{MW} - \text{MW}_1 \\ = 28 - 22.5 \\ = 5.5$$

$$\text{MVAR}_2 = \text{MVAR} - \text{MVAR}_1 \\ = 21 - 10.9 \\ = 10.1$$

$$\text{MVA}_2 = \sqrt{(\text{MW}_2)^2 + (\text{MVAR}_2)^2} \\ = \sqrt{(5.5)^2 + (10.1)^2} \\ = 11.5$$

$$\cos \phi_2 = \frac{5.5}{11.5} = 0.478 \text{ (lag.)} \quad (\text{Ans})$$

* Introduction to Synchronous motor :-

- A synchronous motor is a machine which converts electrical energy into mechanical energy that rotate at a constant speed equal to synchronous speed.
- An alternator can run as a synchronous motor if A.c supply is given to armature winding and D.c supply is given to the field winding such type of motor is known a synchronous motor.

→ Some important Feature of Synchronous motor are given below.

- It runs either synchronous or not at all
- It runs at constant speed.
- The only way to change the synchronous speed is to change the supply frequency (since $N_s = \frac{120F}{P}$) where N_s is synchronous speed
- It can not be self started.

→ Synchronous motor - General :-


- A synchronous motor figure is electrically identical with an alternator or A.c generator.
- The given synchronous machine may be used, atleast theoretically as an alternator, when driven mechanically or as a motor, when driven electrically, just as in the case of d.c machines.
- Most Synchronous motor are rated between 150kw to 15MW and run at speed ranging from 150 to 1800 R.P.M.

→ Some characteristic features of a synchronous motor are worth noting:-


- It runs either at synchronous speed or not at all i.e., while running it maintains a constant speed.
- The only way to change its speed is to vary supply frequency (below $\omega_s = \frac{120f}{P}$)
- It is not inherently self-starting. It has to be run up to synchronous speed by some means before it can be synchronized to the supply.

Classification of A.C. Motors :-


A.C. motors are classified based on different factors such as




- A.C. motors are classified based on working principle




- A.C. motors are classified based on speed.



- A.C. motors are classified on structural features.



Classification according to location



Advantage of synchronous motor :-

- Speed is constant and independent of load.
- Power factor can be controlled easily.
- Motor can work at lagging, leading and unity power factor.

Disadvantage :-

- It is not a self starting motor.
- It requires D.C. excitation.
- Initial cost is very high.
- It can not be used for variable speed drives.
- It has a tendency to hunt.


Application of synchronous motor :-

- Constant speed application like clocks, air compressors, centrifugal pumps, blowers, paper mill and teleprinters.
- Improving voltage regulation of long transmission line.
- Frequency changers.


* Production of rotating Magnetic field :-

- The stator of the induction motor has 3-Φ winding on the inner periphery and are spread over all the slots of the stator.
- The 3-Φ winding when fed with 3-Φ current displaced in time by 120° they produce a resultant magnetic field which rotates in a space or through actual magnetic pole being rotated mechanically, inside the stator.

- A 3- ϕ 2 pole stator having 3 identical windings placed 120° space degree apart is shown in figure




(Three phase 2-pole stator winding)



(Three phase waveform)

- The assumed positive direction of flux :-



(Vector diagram)

- Let the maximum value of flux due to any one of the 3-Φ be Φ_m
- The resultant flux Φ_R at any instant is given by the vector sum of the individual flux Φ_1 and Φ_2 , Φ_3 due to each of the 3-Φ at that instant.
- Consider the value of Φ_R at 4 instant $\frac{1}{6}$ time - Period apart, corresponding to point marked 0, 1, 2, and 3 shown

when

$$\theta = 0^\circ$$

$$\Phi_1 = 0 \quad \Phi_2 = \frac{\sqrt{3}}{2} \Phi_m, \quad \Phi_3 = \frac{\sqrt{3}}{2} \Phi_m$$

- The vector for Φ_2 is in a direction opposite to the direction assumed true.
- at instant $\theta = 0^\circ$ phase ϕ_2 is negative.

Hence,

$$\Phi_R = 2 \times \frac{\sqrt{3}}{2} \Phi_m \cos \frac{60^\circ}{2}, \quad \Phi_R = \sqrt{3} \times \frac{\sqrt{3}}{2} \Phi_m = \frac{3}{2} \Phi_m$$



when


$$\theta = 60^\circ \text{ point } 1 \quad \Phi_{R1} = \frac{\sqrt{3}}{2} \Phi_m$$

$$\Phi_2 = -\frac{\sqrt{3}}{2} \Phi_m$$

$$\Phi_R = 2 \times \frac{\sqrt{3}}{2} \Phi_m \cos 30^\circ = \sqrt{3} \times \frac{\sqrt{3}}{2} \Phi_m = \frac{3}{2} \Phi_m$$

- It is found that resultant flux Φ_R again has a magnitude $\frac{3}{2} \Phi_m$
- But has rotated clockwise through an angle 60°





when,

$\theta = 120^\circ$ i.e., corresponding to point 2

$$\Phi_1 = \frac{\sqrt{3}}{2} \Phi_m, \Phi_2 = 0, \Phi_3 = -\frac{\sqrt{3}}{2} \Phi_m$$

Proceeding on the same line as for I and II above it can be found that

$\Phi_R = \frac{3}{2} \Phi_m$ hence again resultant flux Φ_R at the same magnitude.

But has further rotated clockwise through an angle of 60°

$\theta = 180^\circ$ corresponding to point 3

$$\Phi_1 = 0, \Phi_2 = \frac{\sqrt{3}}{2} \Phi_m, \Phi_3 = -\frac{\sqrt{3}}{2} \Phi_m$$

hence again resultant flux on the same.

magnitude $\frac{3}{2} \Phi_m$

And has rotated clockwise through an additional angle of 60° or through an angle of 180° from the state at $\theta = 0^\circ$

Construction and Classification of Synchronous motor:-

- Construction of synchronous motor is same as that of the synchronous generator
- Major part of synchronous motor

Stator frame
Stator core
Stator winding

Stator or Armature.

Magnetic pole and field winding
Slip ring

Field system


Brush and Brush holder

Spider

Exciter

Shaft and bearing

ROTOR



Stator frame :-

- It is the outer most part of the machine. It is made of cast iron or cast steel or welded steel plates.
- It is main function to give mechanical protection to the entire machine and to hold the core in proper position.


Stator Core:-

- The stator is laminated like a d.c armature core.
- The hole structure is held in a frame on stator frame.
- To minimize the eddy current loss the stator core is laminated.
- The lamination are insulated from each other and have space bet' them allowing the cooling air pass through.
- Slots are provided on the inner periphery of the stator core.

These slots are 3 type.

- 1- Open type or wide open:-
- The open slots are used below coil can be form wound and insulated.
 - This type of slot also facilitate in removal and replacement of defective coil.
 - Disadvantage of distributing the air gap from in to branches of teeth which tend to produce ripple

the EMF wave, forming iron core towards left



wide - open type

2. Semi closed type :-

This semi closed type of slot one better in this respect but do not permit the use of form wound coils.



Semi - closed.

3. Totally closed type:-

- This type of slot does not disturb the airgap flux.
- Increases Inductance of the winding.
- The end connection of the armature winding is all so complicated.




Totally closed.

4. ROTOR :-

- The rotor is a rotating part of alternator. It has many wedge shaped magnetic pole and field winding.
- The field excitation is usually provided from a small

D.C. shunt on Compound generator.

Rotor classified into 2 type




→ Salient pole type motor :-

- It is used in low medium speed alternator.
- The pole are made of steel lamination riveted together and are fixed to the rotor by a dove tail joint.
- The commutator bars are short circuited at both ends by copper ring.
- The field coil are placed on the pole pieces as shown in figure.
- The end of field winding are connected to DC source through a slip ring.

→ Non-Salient pole or smooth cylindrical type :-

- It is used in very high speed alternator mostly driven by steam turbines also called turbo alternator.
- These are of small diameter and of very long axial length.
- less windage loss.
- High spread are obtained 3000 rpm (or 1500 rpm)



Slip rings :-

- Usually hand drawn copper is used for manufacturing slip ring.
- The circuit slip ring are mounted on the same shaft.
- Slip ring facilitate the D.C supply to the field winding through brushes.

Brush and brush holder :-

- Brushes are made of carbon and are placed over the slip ring it is a stationary part.
- brush and brush holder are studied in D.C generator

Spider :-

It's like hub on which magnetic pole are fitted and mounted on the shaft.

Exciter :-

- In alternator the field winding is always required to be excited by a separate D.C supply.

Shaft and bearings :-

- The shaft is made of cast steel.
- Main function is hold the motor.
- It is support in bearing.

Advantage of stationary armature :-

- It is easy to insulate stationary winding.
- Stator winding is not subjected to centrifugal forces.
- It needs only 2 slip rings on D.C side.
- The motor weight is less when compared to stator weight.
- Commutation is not present.


Armature parts along with material:-

Serial No.	Name of the part	Material used.
1	Stator frame	Cast iron cast steel
2	Stator core	Silicon steel on sheet steel
3	Rotor core	Silicon steel
4	Stator and rotor winding	Copper
5	Insulation	Varnish paper
6	Slip rings	Hand drawn copper
7	Brushes	Carbon
8	Shaft	Mild steel or carbon steel
	End cover	Forged steel

Principle of operation

Magnetic locking:-

- Synchronous motor work on the principle of the magnetic locking.
- The 2 unlike poles are brought near each other, if the magnet are strong there exist a tremendous force of attraction between those two poles.
- In such condition the two magnets are said to be magnetically locked due to magnetic locking condition.



- So have the magnetic locking condition, then must exist two unlike pole.

Principle operation of synchronous motor :-

- When a balanced 3- ϕ A.c supply is given to a 3 phase stator winding of synchronous motor it produce a rotating magnetic field (RMF)
- The speed of rotating magnetic field is synchronous speed


$$N_s = \frac{120f}{P}$$

where


f = Supply Frequency

P = No of pole in the stator


- This rotating field can be considered as a North (N_s) and south pole (S_s) at the stator.
- Assume the rotating magnetic field is rotated in clockwise direction due to excitation to the rotor also from rotor pole N_R and S_R .
- Now the rotor will begin to rotate in the anti-clockwise direction.




- Half a cycle later, the position of the stator pole increased N_s is at point Y and S_s is at point X. Now N_s attracts S_R & S_s attracts N_R .
- Hence the rotor tends to rotate in clockwise direction.



- Since the repulsion and attraction take place in every half cycle alternatively, the rotor is stationary.
- Therefore synchronous motor is not starting.
- Now let us consider the position of stator, rotor.
- The stator and rotor pole attract each other.



- Now also there is attraction between the stator and rotor pole. By this magnetic coupling the motor will continue to run at synchronous speed.



Vector diagram of synchronous motor

- Vector diagram of synchronous motor on no load and load
- when the synchronous motor is running on a supply voltage V , back emf is setup in the armature (stator) which oppose the applied voltage.
 - The back emf depends on excitation only as the speed is constant.
 - The result voltage in the armature is the vector diff. ratio of V and E_b .
 - The armature current drawn by the motor $I_a = \frac{V - E_b}{Z_s}$


where

$$Z_s = \text{Synchronous Impedance / phase.}$$


- when the motor is running on no load and if it is assumed then the power taken is zero.



- If the motor is on no load, with its torque, then the diagram is



- The vector E_b falls back by a creation angle α , so a resultant voltage E_R is produced and hence a current I_{a1} flows through the armature and this current makes up the no load losses.
- If now the motor loaded then the motor will further fall back by an angle δ_2 called the load angle.
- Now the resultant voltage E_R is increased to E_R^2 and hence motor draws increased armature current I_{a2} .



Let R_a = Armature Resistance per phase.

X_s = Synchronous reactance per phase.

Z_s = Synchronous Impedance per phase.

$$\text{Station Armature Current/phase } I_a = \frac{E_R}{Z_s}$$

$$I_a = \frac{V - E_b}{Z_s}$$

I_a lags the voltage E_R by angle θ

$$\theta = \tan^{-1} \left(\frac{X_s}{R_a} \right)$$

- If R_a is negligible, $\theta = 90^\circ$ The power input for a star connected three phase motor $= \sqrt{3} V_a I_a \cos \theta$.

where ϕ is angle between v and I_a .

Analysis of phasor diagram:

- Consider a phasor diagram with normal excitation i.e such a current through field winding which will produce flux that will adjust magnitude of E_{bph} same as V_{ph}
- Let α be the load angle corresponding to the load on the motor so form the exact opposing position of E_{bph} with respect to V_{ph} . E_{bph} gets displaced by angle α .
- Vector difference of E_{bph} and V_{ph} give the phasor with current I_a is called E_{Rph} .

NOW,

$$Z_s = R_a + jX_s \angle$$

$$Z_s = |Z_s| \angle \theta_s$$

where R_a = Resistance of stator/phase

X_s = synchronous reactance of stator/phase.


i.e

$$\theta_s = \tan^{-1} \frac{X_s}{R_a}$$

$$\text{and } |Z_s| = \sqrt{R_a^2 + X_s^2} \angle$$

- This angle θ_s is called initial machine angle or an impedance angle.
- The significance of θ_s is that if starting without phasor I_{Rph} lag behind E_{Rph} i.e; I_a by angle θ_s

- Current always lags in inductive impedance with respect to voltage drop across the impedance.
- Practically R_a is very small compared to X_a and θ tends to 90°



$$\Phi = V_{ph} / T_{aph}$$

Φ = Power Factor Angle.

and

$\cos\phi$ = power factor at which motor is working

- The nature of this PF is lagging if I_{aph} lags V_{ph} angle ϕ , while it leading if I_{aph} lead V_{ph} by angle ϕ . Phasor diagram indicating all the details.

→ phasor diagram of under excited synchronous motor on

- The emf induced in the armature E_b .

V = Supply voltage.

E_b = Back EMF

ER = Resultant V of E_b and V

R_a = Armature Resistance per phase in ohm


X_s = Synchronous reactance per phase in ohm

Synchronous impedance $Z_s = \sqrt{R_a^2 + X_s^2}$


- The armature current I_a lags behind the relevant voltage E_R by an angle θ .

Effect of varying load with constant excitation


- Before considering ω to what goes on inside a synchronous motor it is worthwhile to refer briefly to the d.c. motor.
- We have seen that when d.c. motor is running on a supply of say, V on rotating a back emf E_b is setup in its armature conductors.
- The relevant voltage across the armature is $(V - E_b)$
Armature Current $= (V - E_b) / R_a$ flow where R_a is armature ckt resistance.
- The value of depends among other factors on speed of the rotating armature.
- Motor is running on no load and has no losses
 $E_b = V$
- It is seen that vector diff of E_b and V is zero.
Armature current taken (0) zero.



- If motor is on no-load but it has losses then
 - For E_b fall back of θ from 90° is given by



- If now the motor is loaded then motor will function fall back in phase by a greater value of angle α in the load angle coupling angle.






Effect of changing excitation on constant load

- Synchronous motor is operating with normal excitation ($E_b = V$) at unit power factor given load.
- If R_a is negligible or comparable to X_a then I_a lags E_R by 90° and is in phase with V below p.p. is unity.
- The armature is drawing a power of $V \cdot I_a$ per phase which is enough to meet the mechanical load.

on the motor.

- When the load applied the motor remain constant.



Excitation demoted:

- Back emf is reduced to E_{b2} of the same coil angle.
- The new armature voltage E_R1 causes a lagging armature current I_{a1} to flow. I_{a1} is larger than I_a in magnitude incapable of producing necessary power $V I_a$ for carrying the constant load below I_{a1} cos ϕ_1 component of I_{a1} than I_a so that $V I_{a1} \cos \phi_2 < V I_a$

Excitation Principle

- The effect of increasing field excitation where increased E_{B2} is original load angle δ_1 .
- Accordingly load angle decrease from δ_1 to δ_2 which decrease resultant voltage from E_R1 to E_R2 .
- Consequently armature current ~~decrease~~ decrease from I_{A2} to I_{A1} whose I_N - phase component $I_{A2} \cos \delta_2 - I_{A1}$.

Hunting of Synchronous motor



- Hunting is caused due to use of synchronous motor for driving a varying load. This also caused supply frequency pulsating.
- When synchronous motor is loaded, its rotor falls back in phase by the load angle δ .
- When load increase slowly angle δ also increase so that torque produced is more.
- If now load in the motor decreases suddenly then δ also change corresponding new load.
- But in this process motor overshoots.
- Due to this motor start oscillating like a pendulum about its new equilibrium position.
- Like this motor is hunting for the right position when load on the motor changes.
- This is also called as phase swinging, comp. swinging.
- If this frequency of oscillation is equal to the natural frequency they mechanical resonance.

is setup and the amplitude of the swing of the rotor pole relative to the P.D.O. of rotating field become so great that the machine thrown out of synchronism.

- Hunting is an objectionable characteristic of synchronous motor, as it produces severe mechanical stresses as well as large variation in current and power drawn by the motor.

Prevention of Hunting :-

- Hunting is prevented by preventing the damper winding also known as squirrel cage winding on damper grids.
- The damper winding consist of cu bars embedded in the face of the field pole and circuited at the both end by means of end rings.



- When the motor is operating at exactly synchronous speed, there is no relative motion bet' the motor and the stator rotating field and, so no current is induced in this winding.
- But when hunting takes place, there is a relative motion exitt and, therefore, eddy current are setup

- In this winding which flows in such a way so to suppresses or damps out the oscillation.
- The clamping can not prevent hunting completely because their operation depends upon the presence of oscillation motion.
- However, the clamping winding also serves to make the synchronous motor self starting.

Methods of starting :-

Starting methods of synchronous motor :-


- There are three methods for the starting the synchronous motor.
 - a. D.C. motor method
 - b. pony motor method
 - c. Dampen winding method.
- D.C. motor method :-
 - In this method D.C. motor is mechanically coupled to the synchronous motor.
 - The synchronous machine is now working as an alternator.
 - Its excitation is increased till the e.m.f developed is equal to 3- ϕ supply voltage at the busbar.
 - Then the synchronous machine is synchronized with the busbar.
 - At this stage, the D.C. supply to the D.C. motor

switch off now the synchronous machine run as a synchronous motor.

b. Pony motor method:-

- This machine by using a separate small induction motor.
- The small induction motor is called pony motor.
- The help of induction motor to run at the synchronous speed of the synchronous motor.
- To start the synchronous motor the induction motor starts first.
- D.C. supply given to the field winding of synchronous motor.
- The synchronous motor to run at synchronous speed. Then cut off the supply to the induction motor.

c. Damper winding methods:-



- Synchronous motor has salient pole action.
- The slots are made on the pole faces.
- Copper or aluminium bars are inserted in the slots.

- The bars are short circuited at both ends by commutator rings.
- A 3- ϕ supply given to the supply station.
- The synchronous motor provided with a damper winding starts as induction motor. This will run at a speed near the synchronous speed.
- For this purpose reduce voltage may be applied by an auto T/F.

Starting of Synchronous motor

- The synchronous motor are required with damper or squirrel cage winding consisting of bars embedded in the pole shoes and short circuited at both ends.
- This motor starts readily, acting as an induction motor during the starting period.
- Motor starts as an induction motor and while it reaches nearly 95% of its synchronous speed the D.C. field is excited.

Procedure for starting synchronous motor :-

- While starting a modern synchronous motor provide with damper winding following procedure.

 - a) First main field winding is short circuited.
 - b) Reduce voltage with the help of auto T/F at supply station terminal. The motor starts.
 - c) Full supply voltage is applied by cutting out the auto T/F.

Synchronous motor application:-

- Synchronous motor find extensive applications of following uses of service.
- Power factor correction.
- Constant speed, constant load drives.
- Voltage regulation.

Power factor correction:-

- overexcited synchronous motor having leading power factor are widely used for improving power factor of those factors of those power system which employ a large no of induction motor lagging power factor such as welders and fluorescent lights etc.

Constant-speed application:-

- Because of their high efficiency and high speed
- Synchronous motor (above 600 r.p.m) are well suited for load where constant speed is required such as centrifugal pump, belt driven, reciprocating compressors, blowers, line shafts.

Voltage Regulation:-

- The voltage at the end of long transmission line vary greatly especially when large inductive load are present.
- When an inductive load is disconnected suddenly voltage tends to rise considerably above its normal value because of line capacitance.
- By installing a synchronous motor with a device of regulating exc. varying its excitation) this voltage rises control

- when line voltage decreases due to its inductive load, motor excitation is increased thereby raising its p.f. which compensates for the line drop.
- If on the other hand, line voltage rise due to the capacitive effect, motor excitation is decreased thereby making it p.f lagging which helps to maintain the line voltage at normal value.

Three phase induction Motors

Introduction :-

- The induction motor is the most commonly used electrical motors.
- Induction motors is considered to be the working horse of the industry. More than 85% of industrial motors in use to day are induction motors.
- It is an electro-mechanical energy converter & involves the interchange of energy between an electrical & mechanical system.
- The primary quantities involved in the mechanical system are torque and speed, while, the analogous quantities with electrical system are voltage and current respectively, as shown fig.

Electrical system

e, i.

e = voltage

i = current

Coupling field

Mechanical system

T, ω_m

T = Torque

ω_m = Speed

(electromechanical energy conversion)

- The conversion of electrical power to mechanical power takes place in the rotating part of electric motor called the rotor.

- ① Why DC motor is called as a conduction motor ?
- In DC motor the electrical power is conducted directly to the armature through brushes & commutator.
- ② Why it is called as Induction motor ?
- In induction motor, rotor does not receive power by conduction. But by induction in exactly the same way as the secondary of a two winding T/F receives its power from the primary.
- An induction motor can be treated as rotating T/F. That is one in which the primary winding is stationary but the secondary winding is free to rotate.

ADVANTAGES OF INDUCTION MOTOR :-


- (i) It is very simple & construction & reliable in operation.
- (ii) It is self starting.
- (iii) It is very rugged, especially cage type. It requires minimum maintenance.
- (iv) Its efficiency is high & power factor is reasonably good.
- (v) It is quite cheap in cost.

DISADVANTAGES


- Speed decreases with increase in load.
- (ii) Starting torque is inferior to that of DC shunt motor.
- (iii) Methods of its speed control involve more cost.

Production of rotating magnetic field :-

- The stator of the induction motor has 3 Φ winding on the inner periphery & are spread to be accommodated in all the slots of the stator.
- The 3 Φ winding when fed with 3 Φ current displaced in time by 120° , they produce a resultant magnetic flux, which rotates in space as though actual magnetic poles were being rotated mechanically, inside the stator.
- The 3 Φ , 2 Pole stator having 3 identically windings placed 120° space degrees apart is shown in fig. due to 3 Φ windings is shown in below fig.



(3 Φ 2 pole stator winding)



(3 Φ sinusoidal wave form)

→ If the phase sequence of the windings is RYB, then mathematically equations for the instantaneous values of the 3 fluxes Φ_R , Φ_Y & Φ_B can be written as

$$\Phi_R = \Phi_m \sin \omega t$$

$$\Phi_Y = \Phi_m \sin (\omega t - 120^\circ)$$

$$\Phi_B = \Phi_m \sin (\omega t - 240^\circ)$$


Hence ($\because \omega t = 0$)

$$\Phi_R = \Phi_m \sin 0$$

$$\Phi_Y = \Phi_m \sin (0 - 120^\circ)$$

$$\Phi_B = \Phi_m \sin (0 - 240^\circ)$$

→ As windings are identical & supply is balanced the magnitude of each flux is Φ_m .



- Due to phase sequence R-Y-B flux, Φ_Y lags behind Φ_R by 120° & Φ_B lags Φ_Y by 120° . So Φ_B ultimately lags Φ_R by 240° .
- The flux Φ_R is taken as reference while writing the equation.
- Let Φ_R , Φ_Y & Φ_B be the instantaneous value of three fluxes. The resultant flux Φ_{rc} is the phasor addition of Φ_R , Φ_Y & Φ_B .

$$\overline{\Phi}_{rc} = \overline{\Phi}_R + \overline{\Phi}_Y + \overline{\Phi}_B$$

- Let us find Φ_{rc} at the instant 1, 2, 3 & 4 as shown in figure which represented the values of θ as 0° , 60° , 120° , 180° respectively.
- The phasor addition can be performed by obtaining the values of Φ_R , Φ_Y & Φ_B by substituting values of θ in the following equations.

$$\Phi_R = \Phi_m \sin \theta \quad \text{--- ①}$$

$$\Phi_Y = \Phi_m \sin (\theta - 120^\circ) \quad \text{--- ②}$$

$$\Phi_B = \Phi_m \sin (\theta - 240^\circ) \quad \text{--- ③}$$

Case - 1 : $\theta = 0^\circ$:-

Substituting $\theta = 0^\circ$ in eqn 1, 2, 3 we get


Eq ① $\Phi_R = \Phi_m \sin 0^\circ$

$$\boxed{\Phi_R = 0}$$

Eq ② $\Phi_Y = \Phi_m \sin (0 - 120^\circ)$

$$\Phi_Y = \Phi_m \sin (-120^\circ)$$

$$\boxed{\Phi_Y = -0.866 \Phi_m}$$



(Case - 1)

$$\text{Eqn (3)} \Rightarrow \Phi_B = \Phi_m \sin (0 - 240^\circ)$$

$$\Phi_B = \Phi_m \sin (-240^\circ)$$

$\Phi_B = +0.866 \Phi_m$

from the above vector diagram $\Phi_R = 2 \times OD$

From 4 ODB

$$\therefore OD = OB \times \cos 0 \quad (\because \cos 0 = \frac{OD}{OB})$$

$$OD = 0.866 \Phi_m \times \cos 30^\circ$$

$$= 0.75 \Phi_m$$

$\Phi_R = 1.5 \Phi_m$

Substituting equation 5 in 4

$$\Phi_R = 2 \times 0.75 \Phi_m$$

$\Phi_R = 1.5 \Phi_m$

so magnitude of Φ_R is $1.5 \Phi_m$ & its position is vertically upwards at $\theta = 0^\circ$

Case - 2 : $\theta = 60^\circ$:-

Substituting $\theta = 60^\circ$ in eqn 1, 2, 3 we get

Eq-1 $\Rightarrow \Phi_R = \Phi_m \sin 60^\circ$


$\Phi_R = +0.8666 \Phi_m$

$$Eq^n 2 \Rightarrow \phi_y = \phi_m \sin(60 - 120)$$

$$\Phi_4 = -0.866 \Phi_m$$

$$Eq^n 3 \Rightarrow \Phi_B = \Phi_m \sin(60^\circ - 240^\circ)$$

$$\Phi_B = 0$$



(Case 2)

from above vector diagram,

$$\Phi_R = 2 \times 60$$

From 4 ODB

$$\therefore OD = OB \times \cos \theta \quad \left(\because \cos \theta = \frac{OD}{OB} \right)$$

$$OD = 0.75 \text{ dm}$$

Substitute eqn 7(5)6

$$\Phi_{\pi} = -2 \times 0.75 \Phi_m$$

$$\phi_{\text{II}} = 1.5 \phi_m$$

- It can be seen that through its magnitude is 1.5 cm it has rotated to through 60° in space, in clockwise direction, from its previous position.

Case - 3 : $\Theta = 120^\circ$

Substituting $\Theta = 120^\circ$ in equn 1, 2, & 3 we get
Equn 1 : $\Phi_R = \Phi_m \sin 120^\circ$ in the equn

$$\Phi_R = \Phi_m \sin 120^\circ$$


$$\boxed{\Phi_R = 0.866 \Phi_m}$$

$$\text{Equn 2} \Rightarrow \Phi_Y = \Phi_m \sin (120^\circ - 120^\circ)$$

$$\boxed{\Phi_Y = 0}$$

$$\text{Equn 3} \Rightarrow \Phi_B = \Phi_m \sin (120^\circ - 240^\circ)$$

$$\boxed{\Phi_B = -0.866 \Phi_m}$$



From above vector diagram,

$$\Phi_{rc} = 2 \times OD \quad \text{--- (8)}$$

From $\triangle ODB$

$$\therefore OD = OB \times \cos \Theta \quad (\because \cos \Theta = \frac{OD}{OB})$$

$$= 0.866 \Phi_m \times \cos 30^\circ$$

$$OD = 0.75 \Phi_m \quad \text{--- (9)}$$

Substitute equn 9 in 8

$$\Phi_{rc} = 2 \times 0.75 \Phi_m$$

$$\boxed{\Phi_{rc} = 1.5 \Phi_m}$$

The position of Φ_R is such that it has rotated further through 60° from its previous position in clockwise direction & from its position at $\Theta = 0^\circ$, it has rotated through 120° in space in clockwise direction.

Case-4 :- $\Theta = 180^\circ$

Substituting $\Theta = 180^\circ$ in equation 1, 2, 3 we get

$$\text{Eqn} = 1 \Rightarrow \Phi_R = \Phi_m \sin 180^\circ$$


$$\boxed{\Phi_R = 0^\circ}$$

$$\text{Eqn} = 2 \Rightarrow \Phi_Y = \Phi_m \sin (180^\circ - 120^\circ)$$

$$\boxed{\Phi_Y = +0.866 \Phi_m}$$

$$\text{Eqn} = 3 \Rightarrow \Phi_B = \Phi_m \sin (180^\circ - 240^\circ)$$

$$\boxed{\Phi_B = -0.866 \Phi_m}$$



From above vector diagram,

$$\Phi_R = 2 \times 00 \quad \text{--- (10)}$$

From A ODB

$$\therefore OD = OB \times \cos \theta \quad (\cos \theta = \frac{OD}{OB})$$

$$OD = 0.866 \Phi_m \times \cos 30^\circ$$

$$OD = 0.75 \Phi_m$$

Substitute equation 11 into

$$\Phi_R = 2 \times 0.75 \Phi_m$$

$$\boxed{\Phi_R = 1.5 \Phi_m}$$

- So for an electrical half cycle of 180° , the resultant Φ_R has also rotated through 180° . This is applicable for the winding wound for 2 poles.

Conclusion :-

- The resultant flux is of constant magnitude $\frac{3}{2} \Phi_m$ i.e., 1.5 times the maximum value of the flux due to any phase.
- The resultant flux rotates around the stator at synchronous speed given by N_s


$$\boxed{N_s = \frac{120F}{P}}$$

Working principle of 3Φ Induction Motor

- Induction motor works on the principle of electromagnetic induction.
- (Q) What is an electromagnetic induction?
- Whenever a conductor cuts across the magnetic field, an emf is induced in a conductor.

Production of Rotating Magnetic field :-

- When a 3 φ supply is given to the three phase stator winding, a rotating magnetic field of constant magnitude is produced.
- Let direction of rotation of this RMF is clock wise.



(RMF Produced by stator)

- The speed of the RMF is known as synchronous speed.
- It is denoted as N_s in RPM.

$$N_s = \frac{120f}{P}$$

Where,


N_s = Speed of RMF

P = Number of poles for which stator winding is wound.

f = Supply frequency

Induced emf in Rotor :-


- At this instant, rotor is stationary & stator flux is rotating.
- Now stator flux passes through the air gap sweeps past the rotor surface and so cut the rotor conductors.



[Direction of induced emf in Rotor Conductors]

- Due to relative motion b/w the rotating flux & stationary conductors, an emf induces in rotor conductors, according to Faraday law of electro magnetic induction.
- The ratio induced emf circulates the current through the rotor called rotor current.


To find direction of Rotor flux :-



- By applying Flemings right hand rule , the direction of induced emf in the rotor is found to follow in outwards.
- Any current carrying conductor produces its own flux. So factors produce its own flux is called motor flux

The setting up torque for the rotating rotor

- Both the RMF & rotor fluxes interact with each other as shown,



(Interaction of two fluxes)

- On the left of Rotor conductor, two fluxes are in same direction hence add up to get high flux density area.
- On right side, two fluxes cancel each other to produce low flux density area.
- As resultant field lines act as a stretched rubber band, high flux density region exerts a force on conductor towards low density region, i.e. clockwise direction.
- The direction of force can also be found by Flemings left hand rule.

Torque of 3 φ Induction Motor :-

Torque equation :-

- The torque of a 3 φ induction motor depends upon three factors namely flux per pole of stator, rotor current & the P.F.
- The torque in 3 φ induction motor is proportional to the product of above parameters.

$$T \propto \Phi I_2 \cos \phi_2$$

$$T_1 = K \Phi I_2 \cos \phi_2$$

Where,

K = constant

Φ = Flux/pole of the motor stator

I_2 = Rotor current

ϕ_2 = Angle b/w the rotor emf & rotor current

- The rotor emf E_2 is proportional to the flux/pole of the rotor.

Substituting Φ & E_2 on the equation 1

$$\therefore T \propto E_2 I_2 \cos \phi_2$$

- $T = K, E_2 I_2 \cos \phi_2$ which is of induction motor torque equation.

- From the above equation, it is understood that, when ϕ_2 increases $\cos \phi_2$ decrease & therefore the torque decrease.
- When ϕ_2 decrease, $\cos \phi_2$ increase & therefore torque increases.

Starting torque of 3 φ induction motor

Assume,

E_2 = Rotor emf / phase at stand still

R_2 = Rotor resistance / phase

X_2 = Rotor reactance / phase

$$Z_2 = \sqrt{R_2^2 + X_2^2}$$

Z_2 = Rotor impedance / phase at stand still

$$T_2 = \frac{E_2}{Z_2}$$

Rotor current at stand still (I_2)

$$I_2 = \frac{E_2}{\sqrt{R_2^2 + X_2^2}}$$

Rotor power factor,

$$\cos \phi_2 = \frac{R_2}{Z_2}$$
$$= \frac{R_2}{\sqrt{R_2^2 + X_2^2}}$$

Starting torque $T_s = k_1 E_2 T_2 \cos \phi_2$

∴ substitute the value of I_2 & $\cos \phi_2$ on the equation 1

Starting torque (T_s)

$$T_s = k_1 E_2 \frac{\frac{E_2}{\sqrt{R_2^2 + X_2^2}}}{\frac{R_2}{\sqrt{R_2^2 + X_2^2}}} = \frac{k_1 E_2^2 R_2}{R_2^2 + X_2^2}$$

$$= \frac{k_1 E_2^2 R_2}{Z_2^2}$$

$$= \frac{k_1 E_2^2 R_2}{Z_2^2}$$

→ When the voltage applied to the motor is constant, then θ is constant & there by E_2 is constant.

$$\text{Hence starting torque } T_s = K_2 \frac{R_2}{Z_2^2}$$

→ When K_2 is another constant. Here the starting torque of induction motor is directly proportional to motor resistance.

Starting current I_s :-

let, E_2 = motor emf / phase at stand still

R_2 = motor resistance / phase at stand still

X_2 = motor reactance / phase at stand still

Z_2 = motor impedance / phase at stand still

$$Z_2 = \sqrt{R_2^2 + X_2^2}$$

At starting motor current (I_2)

$$I_2 = \frac{E_2}{Z_2} = \frac{E_2}{\sqrt{R_2^2 + X_2^2}}$$

Condition to obtain maximum starting torque
we know,

starting torque,

$$T_s = K_2 \frac{R_2}{Z_2^2}$$

$$T_s = K_2 \frac{R_2}{R_2^2 + X_2^2} \quad (\text{since } Z_2^2 = R_2^2 + X_2^2)$$

→ To obtain maximum starting torque, differentiate the torque w.r.t R_2 & equating to zero.

$$\therefore \frac{dT_s}{dR_2} = \frac{d}{dR_2} K_2 \left(\frac{R_2}{R_2^2 + X_2^2} \right) = 0$$

$$\Rightarrow K_2 \left[\frac{(R_2^2 + X_2^2) - R_2(2R_2)}{(R_2^2 + X_2^2)^2} \right] = 0$$

$$\Rightarrow k_2 \left[\frac{R_2^2 + X_2^2 - 2R_2^2}{(R_2^2 + X_2^2)^2} \right] = 0$$

$$\Rightarrow R_2^2 + X_2^2 - 2R_2^2 = 0$$

$$\Rightarrow -R_2^2 + X_2^2 = 0$$

$$\Rightarrow R_2^2 = X_2^2$$

$$\Rightarrow [R_2 = X_2]$$

Hence the maximum starting torque, the rotor resistance is equal to rotor reactance.

Torque of Induction motor under running condition is

$$T_d E_R I_R \cos \phi_R \quad (\text{since } E_R \propto \phi)$$

$$\textcircled{1} \quad T_d \phi_R I_R \cos \phi_R \quad \text{--- ①}$$

where,

E_R = Rotor induced emf / phase under running condition

$$E_R = SE_2$$

I_R = Rotor current / phase under running condition

$$I_R = \frac{E_R}{Z_R} \quad \text{--- ②}$$

$$Z_R = \sqrt{R_2^2 + (S X_2)^2}$$

Put Z_R & E_R value on Equⁿ ②

$$I_R = \frac{S E_2}{\sqrt{R_2^2 + (S X_2)^2}}$$

$$\therefore \cos \phi_R = \frac{R_2}{Z_R} = \frac{R_2}{\sqrt{R_2^2 + (S X_2)^2}}$$

∴ under running condition, the equation 1 becomes

$$T \propto \Phi \frac{SE_2}{\sqrt{R_2^2 + (sx_2)^2}} \times \frac{R_2}{\sqrt{R_2^2 + (sx_2)^2}}$$

∴ By introducing constant K

$$\therefore T = \frac{K \Phi SE_2 R_2}{R_2^2 + (sx_2)^2}$$

But $E_2 \propto \Phi$

∴ Hence,

$$T = \frac{K_1 S E_2^2 R_2}{R_2^2 + (sx_2)^2}$$

where,

$$K_1 \text{ is another constant} = \frac{3 \times 60}{2\pi N_s}$$

(where N_s = syn. speed in rpm)

Condition for maximum torque at running condition :-

The torque under running condition is

$$T_{\text{run}} = \frac{k_1 S E_2^2 R_2}{R_2^2 + (sx_2)^2}$$

→ To get maximum torque, differentiate the torque w.r.t. slip & equating to zero.

$$\therefore \frac{d}{ds} \left(\frac{k_1 S E_2^2 R_2}{R_2^2 + (sx_2)^2} \right) = 0$$

$$\Rightarrow \frac{k_1 R_2 E_2^2 \{ [R_2^2 + (sx_2)^2] 1 - sx_2^2 \cdot (2s) \}}{[R_2^2 + (sx_2)^2]^2}$$

$$\Rightarrow R_2^2 + (sx_2)^2 - 2s^2 x_2^2 = 0$$

$$\Rightarrow R_2^2 - s^2 x_2^2 = 0$$

$$\Rightarrow R_2^2 = s^2 x_2^2 \Rightarrow \boxed{R_2 = sx_2}$$

Problem -1

A 50 Hz, 8 pole induction motor has a full load slip of 4%. The rotor resistance & reactance are $0.01\ \Omega$ & $0.01\ \Omega/\text{phase}$ respectively. Find the ratio of maximum to full load torque & speed at which maximum torque occurs.

Solution :-

$$\text{No of poles (P)} = 8$$

$$\text{Frequency (f)} = 50 \text{ Hz}$$

$$\text{Synchronous Speed (N_s)} = \frac{120f}{P}$$

$$= \frac{120 \times 50}{8} = 750 \text{ RPM}$$

$$\text{Full load slip } S_f = 4\%$$

$$\Rightarrow S_f = 0.04$$

$$\text{Rotor resistance (R}_2) = 0.01\ \Omega/\text{phase}$$

$$\text{Stand still motor reactance (x}_2) = 0.01\ \Omega/\text{phase}$$

The ratio of max^m to full load torque

$$\frac{T_{\max}}{T_{FL}} = \frac{a^2 + S_f^2}{2aS_f}$$

where,

$$a = \frac{R_2}{x_2} = \frac{0.01}{0.01} = 1$$

$$\therefore \frac{T_{\max}}{T_{FL}} = \frac{1^2 + (0.04)^2}{2 \times 1 \times 0.04}$$

$$= 12.52$$

$$\text{Slip for maximum torque } S_m = a = \frac{R_2}{x_2} = 1$$

speed at maximum torque $N_m = N_s(1 - s_m)$

$$N_m = 750(1-1) \approx 0$$

$$N_m = 0 \text{ (Ans)}$$

Problem - 2 :-

The rotor resistance & stand still reactance per phase of a 3 phase slip ring induction motor are 0.02Ω & 0.01Ω respectively. What should be the value of the external resistance per phase to be inserted in the rotor circuit to give maximum torque at starting.

Solution :-

Rotor resistance (R_2) $\approx 0.02 \Omega/\text{phase}$
stand still rotor reactance (x_2) $\approx 0.1 \Omega/\text{phase}$
starting torque (T_{st}) $= T_{max}$

$$\frac{T_{st}}{T_{max}} = \frac{2a}{1+a^2} = 1$$

$$a^2 - 2a + 1 = 0$$

$$\Rightarrow a = 1$$

let be r the external resistance
then (R_2+r) will be the total resistance.

$$a = \frac{R_2+r}{x_2} = 1$$

$$r = x_2 - R_2$$

$$= 0.1 - 0.02$$

$$= 0.08 \Omega/\text{phase}$$

External resistance to be added
 $r = 0.08 \Omega/\text{phase}$

Slip torque characteristics of 3 φ Induction Motor :-

- The torque ' T ' of a 3 φ induction motor is given by

$$T = \frac{K \Phi S E_2 R_2}{R_2^2 + (S X_2)^2}$$

where,

Φ = flux


S = slip

E_2 = Rotor induced emf / phase at stand still

R_2 = Rotor resistance / phase

X_2 = Rotor Reactance / phase at stand still

K = a constant



[Speed Torque characteristics of 3 φ Induction Motor]

- The slip torque curve for various ranges of R_2 with R_2 are drawn,
- For slip values ranging from 0 to 1 these curves are drawn.

→ Using the above relation, the following cases are considered.

Case-1 :-

→ From the above relation, when $s=0$ then the torque T is also zero. Therefore the curves start from origin $(0,0)$ as shown in figure.

case-2 :-

- When the speed of the rotor is near the synchronous speed, then the slip s value is very small. Therefore the term sE_2 is small.
- On comparing this value with R_2 the value sE_2 is negligible. Hence the torque eqn becomes

$$T_2 = \frac{K\phi sE_2 R_2}{R_2^2}$$

$$\Rightarrow T \propto \frac{s}{R_2}$$

→ Since ϕ, E_2 are constants or, $T \propto s$, If R_2 is constant.

→ From this it is understood that at low value of the slip the torque - slip curve is more or less a straight line.

case-3 :-

- When the load on the motor increases the rotor speed falls down. Then the slip values increases.
- From the above relation it is seen that when slip ' s ' increases the torque ' T ' also increases.

- The torque will attain a maximum value at $s = (R_2/x_2)$. This torque is called pull out or break down or stalling torque.
- Further increases in load on the motor cause the slip to increase still more.
- For higher values of slip, the term (sx_2) is more in value. Hence at higher values of slip R_2 is negligible as compared to (sx_2) .
- Then the torque eqn becomes :-

$$T_d \propto \frac{1}{(sx_2)^2}$$

$$T_d \propto \frac{1}{s^2} \quad (\text{since } \Phi, E_2 \text{ are constant i.e., } x_2 \text{ is constant})$$

$$T_d \propto \frac{1}{s}$$

- Therefore for higher of slips the torque slip curve is a rectangular hyperbola.
- For various values of R , the family of torque slip curve is as shown in fig.
- From these curves it is clear that beyond the point of max^m torque, the increased load on the motor results in a decrease in torque developed.
- Any further increase in load on the motor results, the motor slowing down & it finally stops.
- The speed of the motor comes to zero, when the slip reaches to 1.

- If the load on the motor is too much, the motor speed comes to zero & it stops. Then slip,

$$s = \frac{N_s - N}{N_s} \text{ & equals to 1.}$$
- The stable operating region of the motor lies for the slips value $s=0$ & that corresponding to maximum torque.
- The operating region is hatched area shown in the figure.
- The unstable operating region of motor lies for the slip $s=1$ that corresponds to maximum torque.
- From the torque-slip curves, the following points are noticed :-
- Maximum torque T_{max} remains same & is independent of the rotor resistance.
- The slip for maximum torque increases with increase in rotor resistance.
- Starting torque increases with increase in Rotor Resistance.

Construction of 3 φ Induction Motors :-


- An induction motor consists of two main parts namely,
 - (a) Stator
 - (b) Rotor
 Rotor consists of two types.
 - (i) Squirrel cage rotor
 - (ii) Phase wound or slip ring motor.
- The stator construction is same for both the type of induction motor. The difference in both the type of motors is only in the construction of the rotor.

Construction of squirrel cage induction motor :

Motor employing this type of rotor is called squirrel cage induction motor.

Squirrel cage rotor :-

- Almost 90% of induction motors have the squirrel cage type rotors.
- The rotor is simplest, rugged construction & indestructible.



(squirrel cage rotor)

- The parts of squirrel cage motor are
- (a) Rotor core
 - (b) Rotor bars
 - (c) End ring.

(a) Rotor core :-

- The rotor consists of a cylindrical laminated core with parallel slots for carrying the rotor conductors.
- Rotor core is made up of high quality low-loss silicon steel laminations & flash enamelled on both sides.

(b) Rotor bars :-

- The rotor conductors are not wirey but they consist of heavy bars of copper, aluminium or an alloy.
- One bar is placed in each slot.
- These rotor bars are brazed, electrically welded or bolted to two heavy & stout short circuiting end rings thus giving a rotor that will look like squirrel cage. Hence the name is squirrel cage motor.

(c) End ring :-

- All the ends of the copper bars of each sides are short circuited by cu. end rings to form a closed circuit.
- Hence in this type of rotors, it is not possible to add any external resistance in series with the rotor circuit for starting or speed control.

- (iii) Phase wound or slip ring rotor :-
- The structural details of 3 Φ wound rotor are follows.
- (a) motor core & winding
 - (b) slip ring
 - (c) starting resistance.

(a) motor core & winding :-

- A wound rotor has a laminated core with slots on its outer surface.
- These slots carry 3 phase rotor winding which is similar to the stator winding.
- Both the stator & rotor windings are designed for the same number of poles.
- The 3 Φ rotor winding is usually star connected.

(b) Slip ring :-

- The 3 ends of the rotor winding are connected to the slip rings mounted on the motor shaft.
- So in this type of rotor, the external resistance can be added with the help of brushes & slipring arrangement in series with each phase of the rotor winding.

(c) Starting resistance :-

- At the time of starting, additional resistance in the motor ckt is induced to have higher starting torque.
- When the motor is in running condition the slip rings are short circuited by means of a metal collar which is

pushed along the shaft & connects all the slip ring together.

- At a same time, brushes are also lifted from the slip rings to reduce wear & tear of the brushes due to friction.

Applications of slip ring motor :-

- High starting torque of induction motor is preferred for
 - Hoists
 - Cranes
 - compressors
 - lifts
 - Elevators

Application Of squirrel cage motors :-

- Blowers
 - water pumps
 - printing machines
 - Drilling machines
 - lathe machines
 - Grinders
 - Driving fans
-

Slip & slip speed

Slip speed :-

The slip speed is defined as the difference between the synchronous speed (N_s) & the actual speed of the motors, (N)

$$\boxed{\text{Slip speed} = N_s - N}$$

Slip :-

The slip is defined as the difference b/w the synchronous speed (N_s) & the actual speed of the motor (N), expressed as a fractional of synchronous speed.

$$\boxed{\text{Slip, } s = \frac{N_s - N}{N_s}}$$

$$\boxed{1. \text{ slip, } \gamma_s = \frac{N_s - N}{N_s} \times 100}$$

At running condition :-

The actual speed of the motor can be expressed as

$$S = \frac{N_s - N}{N_s}$$

$$\Rightarrow S N_s = N_s - N$$

$$\Rightarrow N = N_s - S N_s$$

$$\Rightarrow \boxed{N = N_s (1 - s)}$$

At start (or) stand still condition $N=0$

$$\therefore \text{Slip, } s = \frac{N_s - N}{N_s}$$

$$\Rightarrow s = \frac{N_s - 0}{N_s}$$

$$\Rightarrow s = \frac{N_s}{N_s} = 1$$

$\Rightarrow s = 1$ (This is Maximum value of Slip)

Slip can not be zero :-

When, $s = 0$

$$\Rightarrow s = \frac{N_s - N}{N_s}$$

$$\Rightarrow 0 = \frac{N_s - N}{N_s}$$

$$\Rightarrow N_s = N \quad (\text{The torque is zero})$$

Problem :-

A slip ring induction motor runs at 290 rpm at full load when connected to 50 Hz supply. Determine the number of poles & slip.

Sol

Given Data

$$f = 50 \text{ Hz}$$

full load speed of motor $N = 290 \text{ rpm}$

To find :-

Number of poles (P) = ?

$$\text{Slip } (s) = 2$$

Solution :-

Assume synchronous speed $N_s = 300 \text{ rpm}$.

$$\text{Number of poles } (P) = \frac{120f}{N_s}$$

$$= \frac{120 \times 50}{300}$$

$$\Rightarrow P = 20$$

$$\begin{aligned} \text{Slip } (s) &= \frac{N_s - N}{N} \times 100 \\ &= \frac{300 - 290}{300} \times 100 \\ &= \frac{100}{300} \\ &= 3.33\% \end{aligned}$$

Result

$$P = 20$$

$$s = 3.33\%$$

Relationship between rotor input, rotor copper losses & rotor output :-

let P_2 = Rotor i/p

P_C = Rotor copper losses

P_m = Gross mechanical power developed
on Rotor O/P

T_g = Gross torque developed by the
rotor in N-m.

→ The actual torque available at the shaft
called as shaft Torque or we feel Torque
 T_{sh} .

(Gross Torque)

Shaft Torque (T_{sh}) = $T_g - \text{Torque loss due}$
to friction loss.

→ Now i/p to the rotor is through the air
gap with the help of rotating magnetic
field which is rotating at a speed of ' N_s '
RPM.

→ To motor i/p can be expressed in terms
of gross torque T_g & speed as

$$P_2 = \frac{2\pi N_s T_g}{60} \text{ watts} \quad \text{--- (1)}$$

→ Now torque developed remains same, but the
rotor O/P which is gross mechanical power
developed, P_m is at a Speed ' N ' RPM.
So from O/P side we can write

$$P_m = \frac{2\pi N T_g}{60} \text{ watt} \quad \text{--- (2)}$$

we know that rotor copper losses

$$P_C = P_2 - P_m = \frac{2\pi T_q}{60} (N_s - N) \quad \text{--- (3)}$$

Dividing equation 3 by 1, we get

$$\therefore \frac{P_C}{P_2} = \frac{\frac{2\pi T_q}{60} (N_s - N)}{\frac{2\pi T_q}{60} \times N_s}$$

$$\Rightarrow \frac{P_C}{P_2} = \frac{N_s - N}{N_s}$$

$$\Rightarrow \frac{P_C}{P_2} = \text{slip (s)}$$

$$\Rightarrow P_C = SP_2 \quad \text{--- (4)}$$

So rotor cu. loss are slip times the rotor i/p.

→ Now gross mechanical power delivered

$$P_m = P_2 - P_C$$

$$\Rightarrow P_m = P_2 - SP_2$$

$$\Rightarrow P_m = (1-s) P_2 \quad \text{--- (5)}$$

→ So gross mechanical power developed is $(1-s)$ times rotor i/p.

Dividing eqn 4 by 5 we get

$$\frac{P_C}{P_m} = \frac{s}{1-s} \quad \text{--- (6)}$$

From the above, it can be concluded that

$$P_2 : P_C : P_m = 1 : s : 1-s$$

Problem

The power i/p to a 3φ induction motor is 60 kW. The total stator losses is 1 kW. Find the rotor copper loss /phase if the motor is running with slip (s) of 3%.

Solution

Rotor i/p or stator i/p (P_{in}) = 60 kW

Total stator losses = 1 kW

$$\text{Slip (s)} = 3\% = 0.03$$

Rotor i/p

$$P_2 = \text{stator i/p} - \text{stator losses}$$

$$\Rightarrow P_2 = 60 - 1$$

$$\Rightarrow P_2 = 59 \text{ kW}$$

$$\Rightarrow P_2 = 59 \times 10^3 \text{ W}$$

Rotor copper losses

$$P_C = SP_2$$

$$\Rightarrow P_C = 0.03 \times 59 \times 10^3$$

$$\approx 1170 \text{ W}$$

$$\text{Rotor copper loss / phase} = \frac{1170}{3} = 390 \text{ W.}$$

Problem :-

The rotor emf of a 3φ, 6 pole, 400 V, 50Hz induction motor alternates at 3 Hz. Compute the speed & % slip of the motor.

Find the rotor copper loss /phase if the full i/p to the rotor has 111.9 kW.

Solution :-

$$\text{No. of Poles (P)} = 6$$

$$\text{frequency (f)} = 50 \text{ Hz}$$

$$\text{synchronous speed (N}_s = \frac{120f}{P}$$

$$\Rightarrow N_s = \frac{120 \times 50}{6}$$

$$\Rightarrow N_s = 1000 \text{ RPM}$$

$$\text{Rotor frequency (f}_r) = 3 \text{ Hz}$$

$$\text{Slip (s)} = \frac{f_r}{f} = \frac{3}{50} = 0.06$$

$$\therefore \text{slip} = 6\%$$

$$\text{Motor speed (N)} = N_s (1-s)$$

$$\Rightarrow N = 1000 (1 - 0.06)$$

$$\Rightarrow N = 940 \text{ RPM}$$

Rotor type

$$P_2 = 111.9 \text{ kW}$$

Rotor copper loss

$$P_C = SP_2$$

$$\Rightarrow P_C = 0.06 \times 111.9$$

$$\Rightarrow P_C = 6.714$$

$$\text{ROTOR cu loss / phase} = \frac{6.714}{3}$$

$$= 2.238 \text{ kW}$$

Rotor cu loss / phase $\underline{\underline{2.238 \text{ kW}}}$.

Starting Methods of 3Φ induction Motor :-

Starting of induction motor :-

- The plain induction motor is similar in action to a polyphase T/F with a short-circuited rotating secondary.
- The normal supply voltage is applied to the stationary motor, then as in the case of a T/F, a very large initial current is taken by the primary, at least for a short while.
- The exactly similar conditions exist in the case of a D.C. motor, if it is thrown directly across the supply lines.
- Induction motors, when directly switched takes five to seven times their full load current & developed only 1.5 to 2.5 times their full load torque.
- The initial excessive current is objectionable because it will produce large line voltage drop that during, will affect the operation of other electrical equipment connected to the same lines. Hence, it is not advisable to line start motors of rating above 25 KW to 40 KW.
- The starting torque of an induction motor can be improved by increasing the resistance of the rotor circuit.
- This can be easily feasible in the case of slip ring motors but not in the case of squirrel cage motors.
- The initial inrush of current is controlled by applying a reduced voltage to the

Starting Methods of 3Φ induction Motor :-

Starting of induction motor :-

- The plain induction motor is similar in action to a polyphase T/F with a short-circuited rotating secondary.
- The normal supply voltage is applied to the stationary motor, then as in the case of a T/F, a very large initial current is taken by the primary, at least for a short while.
- The exactly similar conditions exist in the case of a D.C. motor, if it is thrown directly across the supply lines.
- Induction motors, when directly switched takes five to seven times their full load current & developed only 1.5 to 2.5 times their full load torque.
- The initial excessive current is objectionable because it will produce large line voltage drop that during, will affect the operation of other electrical equipment connected to the same lines. Hence, it is not advisable to line start motors of rating above 25 kW to 40 kW.
- The starting torque of an induction motor can be improved by increasing the resistance of the rotor circuit.
- This can be easily feasible in the case of slip ring motors but not in the case of squirrel cage motor.
- The initial inrush of current is controlled by applying a reduced voltage to the

stator during the starting period, full normal voltage being applied when the motor has run up to speed.

Direct switching or line starting of induction motor :-

It has been shown earlier that

$$\text{Rotor i/p} = 2\pi N_s T \\ = KT$$

Also, motor cu. loss = $S \times$ rotor input

$$\therefore 3I_2^2 R_2 = S \times KT$$

$$\therefore T \propto I_2^2 / S \quad (\text{if } R_2 \text{ is the same})$$

Now $I_2 \propto I_1$,

$$\therefore T \propto I_1^2 / S \quad (\text{or}) \quad T \propto K I_1^2 / S$$

→ At starting moment :-

$$S = 1$$

$$\therefore T_{st} = K I_{st}^2$$

where,

I_{st} = starting current

S_f = full load slip

If, I_F = normal full-load current

Then,

$$T_F = K I_F^2 / S_f$$

$$\therefore \frac{T_{st}}{T_F} = \left(\frac{I_{st}}{I_F} \right)^2 S_f$$

→ When motor is direct-switched on to normal voltage, then starting current is the short-circuit current I_{sc} .

$$\therefore \frac{T_{st}}{T_F} = \left(\frac{T_{sc}}{T_F} \right)^2 S_f$$

$$\Rightarrow \frac{T_{st}}{T_F} = a^2 S_f$$

where, $a = T_{sc}/T_F$

Suppose in a case ..

$$T_{sc} = 7T_F$$

$$S_f = 4\%$$

$$S_f = 0.04$$

then,

$$\frac{T_{sc}}{T_F} = 7^2 \times 0.04$$

$$\Rightarrow \frac{T_{st}}{T_F} = 1.96$$

\therefore Starting torque = 1.96 \times full - load Torque

→ We find that with a current as greater as seven times the full - load current, the motor develops a starting torque which is only 1.96 times the full - load value.


Types OF Stators :-

- The expression of rotor current it can be seen that the current at start can be controlled by reducing E_2 which is possible by supplying reduced voltage at start or by increasing the rotor resistance R_2 at start.
- The second method is possible only in case of slip ring induction motors.

- the various types of starters based on the above two methods of reducing the starting current.
 - (i) Stator resistance starters.
 - (ii) Auto Transformers starters.
 - (iii) Star-delta starters.
 - (iv) Rotor-resistance starters.
 - (v) Direct on line starters.


Plugging in 3Φ Induction Motor :-

- plugging or reverse current breaking condition is achieved by reversing the direction of the field.
- The direction of rotation of the field in the air gap depends on the phase sequence connections of the stators' windings.
- Effect of φ sequence on direction of rotation



[Effect of φ sequence on direction]
of rotation airgap field

- When the 3Φ stators' windings are connected in the RYB sequence, the air gap field rotate in one direction at synchronous speed.
- When the sequence of the stators' winding is change in RBY the field reverse its direction.
- The interchanging the supply of any two terminal of the motor as shown fig.



(Connections for plugging of a
3 ϕ induction motor)

→ The rotor & stator magnetic field rotate in opposite directions. Then the slip of the motor is given by:


$$S = \frac{\omega_s - (\omega_s)}{\omega_s}$$

$$\Rightarrow S = \frac{\omega_s + \omega}{\omega_s}$$

$$\Rightarrow S = 1 + \frac{\omega}{\omega_s}$$

→ The slip is more than 1 & full speed it is nearly equal to 2.

→ The speed torque characteristics of the motor during plugging is shown in fig.



(Speed torque characteristics)
for plugging

- The direction of torque developed is reversed and the motor begins to slow down till its speed becomes zero.
- The motor is disconnected from the supply at this instant, otherwise the motor will accelerate in the reverse direction in the motoring condition.
- Plugging is also known Counter current breaking.

ADVANTAGES :-

- Simple control scheme, except for the requirement of a relay to stop the motor.
- Uniform current loading of all the 3φ during the process of braking.

DIS ADVANTAGES :-

- Energy loss is high.
- Increased heating of the machine.
- Possibility of the motor running in reversed direction in case of malfunctioning of the relay used to stop the motor.
- Appearance of very high voltages at the slip rings.

TYPES OF ENCLOSURE

(ii) Open protected type :-

- These type are suitable for all ordinary commercial purposes where there is no usual exposure of dust or damp.
- The end shields have sufficient openings for inspection of general conditions, brushes, commutator or the winding.

(iii) Screen protected enclosure :-

- A motor is said to be totally enclosed when it is so closed in all respect as to prevent air circulation between the inside & outside the case.
- The figure shows the general view of one such enclosure.

(iii) Screen protected enclosure :-

- These are ventilated enclosures having openings in the frame but are protected with a wire screen or with an expanded metal or other suitable perforated cover.
- The area of each aperture in the screen or cover would be sufficient for cooling & protection.
- The figure shows the general view of one such enclosure.

Speed control :- of 3 φ induction Motor :-

① Supply voltage control :-

→ We know that $T \propto \frac{SE_2^2 R_2}{R_2^2 + (Sx_2)^2}$


Now E_2 the motor induced emf at stand still depends on the supply voltage V .

$$\therefore E_2 \propto V$$

Also for low slip region, which is operating region of the induction motor $(Sx_2)^2 \ll R_2$ & hence can be neglected.

$$\therefore T \propto \frac{SV^2 R_2}{R_2^2} \propto SV^2 \text{ for constant } R_2$$

- The supply voltage is reduced below rated value, as per equation torque produced also decreases.
- To supply the same load it necessary to develop same torque hence value of slip increases so that torque produced remains same.
- Slip increases means motor reacts by running at lower speed, to decreases in supply voltage so motor produced the required load torque at a lower speed.
- The speed torque characteristics for the motor using supply voltage control are shown in fig.



[Speed - Torque curves for motor with voltage control]

- In this method, due to reduction in voltage, current draw by the motor increases.
- Large change in voltage for small changes in speed is required is the biggest disadvantage. Due to increased current, the motor may get over heated.
- Additional voltage changing equipment is necessary. Hence this method is rarely used in practice.

② Supply frequency control method :-

The synchronous speed is given.

$$N_s = \frac{120f}{P}$$

- Thus, by controlling the supply frequency smoothly the synchronous speed can be controlled over a wide range. This gives smooth speed control of an induction motor.

But the expression for the air gap flux is given,

$$\Phi_g = \frac{1}{4.44 K_1 T_{ph}} \left(\frac{V}{f} \right)$$

This is according to the emf equation of a T/F.

Where K_1 = Stator winding


T_{ph} = Stator turns / phase.

• V = Supply Voltage

f = Supply frequency.

- It can be seen from the supply frequency is changed. The value of air gap flux also gets affected.

- This may result saturation of stator & rotor cores. Such a saturation leads to sharp increase in the no. load current of the motor.
- It is necessary to maintain air gap flux constant when supply frequency (f) is changed.
- To achieve this, it can be seen from the above expression that along with f, V also must be changed so as to keep (V/F) ratio constant.
- In this method the supply to the induction motor required is variable voltage variable frequency supply & can be achieved by an electronic scheme using converter & inverter circuitry. This is shown in the figure.



(Electronic scheme for V/f control)

- The normal supply available is constant voltage constant frequency AC supply. The converter converts this supply into a DC supply. This DC supply is then given to the inverter.
- The inverter is a device which converts DC supply to variable voltage, variable frequency.

AC supply which is required to keep V/f ratio constant.

- By selecting the proper frequency & maintaining V/f constant, smooth speed control of the induction motor is possible.
- If f is the normal working f. then the fig. shows the torque slip characteristics for the frequency $f_1 > f$ & $f_2 < f$ i.e., for frequencies above the below the normal frequency.
- Another disadvantage of this method is that supply obtained can not be used to supply other devices which require constant voltage. Hence an individual scheme for a separate motor is required which makes it costly.